

| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|------------------|---------|
| 2040 2044 | | C.R. to clean of U.G tank & O.H.tank of water storage | 0.07 | | 0.07 | | |
| 2010-2011 | MAR | tank of R.C. Bldg A ward | 0.07 | 0 | 0.07 | Work in progress | - |
| 2040 2044 | | C.R. work for repair to drain line & remove debries from h. | | | 0.53 | | |
| 2010-2011 | MAR | gully, clean of GSW line to R.C./Sahyog | 0.52 | 0 | 0.52 | Work in progress | |
| 2010-2011 | | C.R. Work for repair to the meter cabin , pump Room R/C Bldg known as Srinathji Bhavan Fort, Mumbai C.R.work repair to vert.PVC soil pipe & repair & replace of | 0.5 | 0 | 0.5 | | |
| 2010-2011 | MAR | G.I.pipe to R.C.Bldg Sahyog | 0.5 | 0 | 0.5 | Work in progress | |
| 2010-2011 | MAR | S.& C. work for all t/s & shop area under A ward for R.C. Bldg Colaba | 0.5 | 0 | 0.5 | Work in progress | |
| 2010-2011 | MAR | S.&C.work for all T/S & shop area under A ward for R.C. Bldg Colaba | 0.5 | 0 | 0.5 | Work in progress | |
| 2010-2011 | MAR | S.R. to R.C.Bldg know Sangam for water proping tretment to terrace A ward | 0.5 | 0 | 0.5 | Work in progress | |
| 2010-2011 | MAR | S.R.work to R.C. Bldg know Sangam repair to external plaster soil pipe, painting & allied work | 0.5 | 0 | 0.5 | Work in progress | |
| 2010-2011 | MAR | Special repair to R.C. Bldg know Sahyog repair to internal plaster work & W.C. bath & allied work | 0.5 | 0 | 0.5 | Work in progress | |
| 2010-2011 | MAR | C.R. work for repairs to floor area of electric cabin & house gully to R.C. Building known as Milan at fort, Mumbai | 0.5 | 0 | 0.5 | Work in progress | |
| 2010-2011 | MAR | C.R. work for repairs to drain line soil PVC pipe and allied work to R/C building known as Milan at fort, Mumbai | 0 | 0.33 | 0.33 | Completed. | |
| 2010-2011 | MAR | S.R. to R/C. Bldg. Garib Nawaj in C ward | 3.39 | 0 | 3.39 | | |
| 2010-2011 | MAR | S.R. to R/C. Bldg. Haji Hanif in C ward | 5.11 | 0 | 5.11 | | |
| 2010-2011 | MAR | S.R. to R/C. Bldg. Rafiya Manzil in C ward | 5.28 | 0 | 5.28 | | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|--|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| 2010 2011 | | PROVIDING ANTITERMITE TREATMENT TO R/C BLDG. "NAZRANA & HAJI HANIF MANZIL" | 0.50 | | 0.50 | | |
| 2010-2011 | MAR | PROVIDING ANTITERMITE TREATMENT TO R/C BLDG. | 0.58 | 0 | 0.58 | | |
| 2010-2011 | MAR | "PUSHPA SADAN" | 0.58 | 0 | 0.58 | | |
| 2010-2011 | MAR | PROVIDING ANTITERMITE TREATMENT TO R/C BLDG. "MEMON MANZIL & GARIB NAWAB MANZIL" | 0.58 | 0 | 0.58 | | |
| 2010-2011 | MAR | PROVIDING ANTITERMITE TREATMENT TO R/C BLDG. "RAJMUDRA & RAFIA MANZIL" | 0.58 | 0 | 0.58 | | |
| 2010-2011 | MAR | R/C BLDG. KNOWN AS "HAJI HANIF MANSION" REPLACEMENT OF DAMAGED REPAIRS TO G I PIPE AND WHEELED STOP TOP | 0.43 | 0 | 0.43 | | |
| 2010-2011 | MAR | RENOVATION OFFICE OF EXECUTIVE ENGINEER C-1 DIV. 2ND FLOOR, ROPA LANE SITUATED AT CHANDANWADI MARIN LINES, MUMBAI. | 6.67 | 0 | 6.67 | | |
| 2010-2011 | | Providing & fixing of Furniture Ex. Eng. In C-3 ward | 7.72 | 0 | 7.72 | | |
| 2010-2011 | | S.R. to R/C Bldg. Known as Haji Hanif in C-1 ward Water Proofing to terrace | 4.45 | 0 | 4.45 | | |
| 2010-2011 | MAR | C.R. work to R/C. bldg. Garib Nawaz at Chimna Butcher Street Providing repair to meter room drainage, system by providing PVC pipe(inspection chamber) | 0.57 | 0 | 0.57 | | |
| 2010-2011 | MAR | C.R. work to R/C. bldg. Garib Nawaz at Chimna Butcher Street Improvement of drainage system Providing GSW pipe PVC pipe & Inspection chamber | 0.58 | 0 | 0.58 | | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|--|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| | | SR work to R/C bldg. Mainoon Manzil, 95/97, Chimna | | | | | |
| | | Butcher Street, Providing enternal plaster & painting work | | | | | |
| 2010-2011 | MAR | & providing PVC pipe. | 5.94 | 0 | 5.94 | | |
| 2010-2011 | MAR | SR work to R/C bldg. known as Tohfa. | 8.13 | 0 | 8.13 | | |
| 2010-2011 | MAR | C.R. WORK TO R.C. GARJANA BLDG. | 0.36 | 0 | 0.36 | COMPLETED | |
| | | C.R. WORK TO R.C. SADBHAVNA BLDG.(Replacement | | | | | |
| 2010-2011 | MAR | of G.I. PVC Pipe & chockup) | 0.24 | 0 | 0.24 | COMPLETED | |
| 2010-2011 | MAR | S.R.WORK TO R.C. VIJAYA COTTAGE 14 ZAOBA WADI | 5.81 | 0 | 5.81 | COMPLETED | |
| | | | 0.01 | | 0.01 | | |
| 2010-2011 | MAR | S.R.WORK TO R.C. AKSHAY BLDG. AT FANAS WADI | 4.99 | 0 | 4.99 | COMPLETED | |
| 2010-2011 | MAR | C.R. TO R.C. BLDG. VALMIKI BLDG. (W.C. PLASTER) | 0.34 | 0 | 0.34 | COMPLETED | |
| 2010-2011 | MAR | S.R. WORK TO R.C. SADBHAVNA BLDG.(INTERNAL STRUCTURAL REPAIRS TO RCC MEMBERS) | 12.1 | 0 | 12.1 | COMPLETED | |
| 2010-2011 | MAD | CR TO CLEANING & WASHING OF U.G. TANK & OG WATER TANK | 0.086 | 0 | 0.086 | COMPLETED | |
| 2010-2011 | | 28-30, 3rd Marine Street | 4.05 | 0 | 4.05 | Completed. | |
| 2010-2011 | | Aashish Apartment- External plaster & painting | 6.55 | 0 | 6.55 | Completed. | |
| 2010-2011 | | Aashish Apartment | 2.4 | 0 | 2.4 | Completed. | |
| 2010-2011 | | Anmol Apartment-Waterproofing | 2.7 | 0 | 2.7 | Completed. | |
| 2010-2011 | | Navbahar- Plaster, painting, P.V.C., G, I, pipe | 5.1 | 0 | 5.1 | Completed. | |
| 2010-2011 | | 62-65, Ist Pathan Street | 4.15 | 0 | 4.15 | Completed. | |
| 2010-2011 | | Navbahar-Waterproofing | 3.1 | 0 | 3.1 | Completed. | |
| 2010-2011 | | Rajmudra-waterproofing | 4.45 | 0 | 4.45 | Completed. | |
| 2010-2011 | | Suryadarshan-Plaster, painting, PVC & G.I. pipes | 4.75 | 0 | 4.75 | Completed. | |
| 2010-2011 | | 28-30, 3rd Marine Street - Waterproofing | 1.7 | 0 | 1.7 | Completed. | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|--|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| 2010-2011 | L MAR | Shital- Plaster, painting, PVC & GI pipes | 6.2 | 0 | 6.2 | Completed. | |
| 2010-2011 | MAR | Nav Bahar- Replacement of Door & Window | 0.59 | 0 | 0.59 | Completed. | |
| 2010-2011 | L MAR | Pushpa Sadan - Replacement Door & window | 0.62 | 0 | 0.62 | Completed. | |
| 2010-2011 | MAR | Antitermite for Parnakuti & 62-65, Pathan St. | 0.65 | 0 | 0.65 | Completed. | |
| 2010-2011 | L MAR | Ambica Sadan-PVC pipe | 0.62 | 0 | 0.62 | Completed. | |
| 2010-2011 | MAR | Ramsadan | 0.57 | 0 | 0.57 | Completed. | |
| 2010-2011 | MAR | Rajmudra- Plaster to ceiling | 0.62 | 0 | 0.62 | Completed. | |
| 2010-2011 | MAR | Ramdsadan - Door & Window-Gr. To Ist | 0.61 | 0 | 0.61 | Completed. | |
| 2010-2011 | MAR | Ramdsadan - Door & Window-2nd to 3rd | 0.61 | 0 | 0.61 | Completed. | |
| 2010-2011 | MAR | Ambica Sadan- Compound Wall & U. G. Tank | 0 | 0 | 0 | In progress | |
| 2010-2011 | MAR | Ganesh Darshan-Drainage lines & I.C. | 0.58 | 0 | 0.58 | Completed. | |
| 2010-2011 | L MAR | Suryadarshan-Drainage line & I.C. | 0.63 | 0 | 0.63 | Completed. | |
| 2010-2011 | L MAR | Samarth Niwas- External & Internal plaster | 0 | 0 | 0 | In progress | |
| 2010-2011 | L MAR | Ambica Sadan- Waterproofing | 2.89 | 0 | 2.89 | Completed. | |
| 2010-2011 | l MAR | SWEEPING & CLEANING OF 783 T/S UNDER D-1 WARD | 0.600 | 0.000 | 0.6 | Completed | |
| 2010-2011 | L MAR | S.R WORK OF EXTERNAL PLASTER & PAINTING TO "ASHRAYA" BLDG UNDER D-1 WARD | 9.130 | 0.000 | 9.13 | Completed | |
| 2010-2011 | L MAR | CR TO PARISHRAM BLDG - REPLACEMENT OF DECAYED DOORS - | 0.620 | 0.000 | 0.62 | Completed | |
| 2010-2011 | l MAR | CR TO PARISHRAM BLDG - REPLACEMENT OF DECAYED WINDOWS - | 0.590 | 0.000 | 0.59 | Completed | |
| 2010-2011 | l Mar | SR WORK OF EXTERNAL & INTERNAL, PLASTER AND PAINTING TO JAY-VIJAY BLDG UNDER D-1 WARD | 9.530 | 0.000 | 9.53 | Completed | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| | | | 5.630 | 0.000 | | Completed | |
| 2010-2011 | | SR WORK OF WATER-PROOFING TO TERRACE OF BLDG "JANAKI NIWAS" UNDER D-1 WARD | | | 5.63 | | |
| 2010-2011 | WIAN | SWEEPING & CLEANING OF 783 T/S UNDER D-1 | 0.560 | 0.000 | 5.05 | Completed | |
| 2010-2011 | MAR | WARD | | | 0.56 | ' | |
| | | CR TO RC BLDG "RAM" - REPAIRS TO LIFT ROOM, | 0.550 | 0.000 | | Completed | |
| 2010-2011 | MAR | HEAD ROOM & ALLIED WORKS | | | 0.55 | | |
| | | | 0.580 | 0.000 | | Completed | |
| | | CR TO RC BLDG "LUV" AT KHADILKAR - | | | | | |
| 2010-2011 | MAR | REPLACEMENT OF DAMAGED DOORS & WINDOWS - | | | 0.58 | | |
| | | CR TO CLEANING & WASHING OF UG & OH TANK OF | 0.230 | 0.000 | | Completed | |
| 2010-2011 | MAR | R/C BUILDINGS IN D-1 DIV. | | | 0.23 | | |
| | | SWEEPING & CLEANING OF 783 T/S UNDER D-1 | 0.560 | 0.000 | | Completed | |
| 2010-2011 | MAR | | 0.220 | 0.000 | 0.56 | Completed | |
| | | CR TO R/C BUILDING HARI-OM IN D-1 DIV REPAIRS | 0.230 | 0.000 | | Completed | |
| 2010-2011 | MAR | TO INSPECTION CHAMBERS CR TO R/C BUILDING HARI-OM IN D-1 DIV | 0.620 | 0.000 | 0.23 | Completed | |
| | | REPLACEMENT OF DAMAGED GI & PVC PIPES, TREE | 0.020 | 0.000 | | completed | |
| 2010-2011 | MAR | CUTTING & WHEELED STOP TAP | | | 0.62 | | |
| 2010 2011 | | CR TO CLEANING & WASHING OF UG & OH TANK OF | 0.060 | 0.000 | 0.02 | Completed | |
| 2010-2011 | MAR | R/C BUILDINGS IN D-1 DIV. | | | 0.06 | | |
| | | CR TO R/C BUILDING SIDDHIVIHAR IN D-1 WARD - | 0.630 | 0.000 | | Completed | |
| | | REPAIRS TO HOUSE GULLI & REMOVAL OF CHOKE | | | | | |
| 2010-2011 | MAR | UP FROM DRAINS | | | 0.63 | | |
| | | CR TO R/C BUILDING KUSH IN D-1 WARD - REPAIRS | 0.640 | 0.000 | | Completed | |
| 2010-2011 | MAR | TO WATER PROOF OF WC & BATH | | | 0.64 | | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS |
|-----------|-------|--|-----------------------------------|------------------------------------|----------------------|----------------|
| 2010-2011 | MAR | SR TO R/C BUILDING PARISHRAM IN D-WARD - WATERPROOFING TO TERRACE & OH TANK, UG TANK | 6.340 | 0.000 | 6.34 | Completed |
| 2010-2011 | MAR | CR TO PARISHRAM IN D-1 WARD - REPLACEMENT OF DAMAGED GI PIPES & REMOVAL OF CHOKE UP OF DRAINAGE LINES & INSPENCTION CHAMBER | 0.230 | 0.000 | 0.23 | Completed |
| 2010-2011 | MAR | CR TO R/C BUILDING LUV-KUSH IN D-1 DIV REPLACEMENT OF DAMAGED GI & PVC PIPES, TREE CUTTING, CLEANING OF DRAINAGE LINES | 0.240 | 0.000 | 0.24 | Completed |
| 2010-2011 | MAR | CR TO R/C BUILDING TRIMURTHI IN D-1 DIV REPLACEMENT OF DAMAGED GATE VALVE & PVC PIPES, TREE CUTTING, CLEANING OF DRAINAGE LINES | 0.250 | 0.000 | 0.25 | Completed |
| 2010-2011 | | CR TO R/C BUILDING SHATRUGHNA IN D-1 DIV REPLACEMENT OF DAMAGED GI & PVC PIPES, TREE CUTTING, CLEANING OF DRAINAGE LINES, PROVIDING BITUMEN | 0.250 | 0.000 | 0.25 | Completed |
| 2010-2011 | | CR TO R/C BUILDING HARI-OM IN D-1 DIV REPLACEMENT OF DAMAGED GI & PVC PIPES, TREE CUTTING & WHEELED STOP TAP, REMOVING CHOKE UP & LEAKAGES | 0.250 | 0.000 | 0.25 | Completed |
| 2010-2011 | MAR | SWEEPING & CLEANING OF 721 T/S UNDER D-1 WARD | 0.560 | 0.000 | 0.56 | Completed |
| 2010-2011 | MAR | SWEEPING & CLEANING OF 721 T/S UNDER D-1 WARD | 0.000 | 0.000 | 0 | In Progress |



| S | REMARKS |
|---|---------|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |



| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|--|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| | | | 0.570 | 0.000 | | Completed | |
| 2010-2011 | MAR | REPAIRS TO UG TANK & ROOM CEILING PLASTER | 0.640 | 0.000 | 0.57 | | |
| 2010-2011 | MAR | IMPROVEMENT IN DRAINAGE SYSTEM | 0.610 | 0.000 | 0.61 | Completed | |
| 2010-2011 | MAR | REPLACEMENT OF DAMAGED/ DECAYED DOORS | 0.510 | 0.000 | 0.51 | Completed | |
| 2010-2011 | MAR | REPLACEMENT OF DAMAGED/ DECAYED DOORS | 0.390 | 0.000 | 0.39 | Completed | |
| 2010-2011 | MAR | REPLACEMENT OF DAMAGED/ DECAYED DOORS | 0.000 | 0.000 | 0 | In Progress | |
| 2010-2011 | MAR | CR TO R/C BUILDING TRIMURTI, BHARAT & PARIJAT IN D-1 DIV REMOVING & REPLACING OF DAMAGED PVC DRAIN WATER PIPES & GI PIPES. | 0.250 | 0.000 | 0.25 | Completed | |
| 2010-2011 | MAR | CR TO R/C BUILDING JANKI NIWAS IN D-1 DIV REPAIRS TO PVC PIPES & GSW DRAINAGE LINE. | 0.250 | 0.000 | 0.25 | Completed | |
| 2010-2011 | MAR | CR TO R/C BUILDING JAY-VIJAY IN D-1 DIV REPAIRS TO GI PIPES & PVC PIPES. | 0.240 | 0.000 | 0.24 | Completed | |
| 2010-2011 | | CR TO R/C BUILDING HARI-OM IN D-1 DIV PROVIDING SHAHABAD STONE IN HOUSE-GULLI | 0.220 | 0.000 | 0.22 | Completed | |
| 2010-2011 | MAR | CR TO R/C BUILDING HARI-OM IN D-1 DIV REPAIRS TO HOUSE GULLI | 0.620 | 0.000 | 0.62 | Completed | |
| 2010-2011 | MAR | CR TO R/C BUILDING LUV - REPAIRS TO OH WATER TANK | 0.000 | 0.000 | 0 | In Progress | |
| 2010-2011 | MAR | PROVIDING ANTI-TERMITE TREATMENT TO OMKAR BLDG | 0.150 | 0.000 | 0.15 | Completed | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|---------|--|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| 2010 2011 | | PROVIDING ANTI-TERMITE TREATMENT TO PARIJAT BLDG | 0.220 | 0.000 | 0.22 | Completed | |
| 2010-2011 | . IVIAK | PROVIDING ANTI-TERMITE TREATMENT TO | 0.160 | 0.000 | 0.22 | Completed | |
| 2010-2011 | MAR | SIDDHIVIHAR BLDG | | | 0.16 | | |
| 2010 2011 | | PROVIDING ANTI-TERMITE TREATMENT TO NIRDHAR | 0.220 | 0.000 | 0.10 | Completed | |
| 2010-2011 | MAR | BLDG | | | 0.22 | | |
| | | CR TO R/C BLDG RAM - REPAIRS TO LIFT ROOM & | 0.000 | 0.000 | | In Progress | |
| 2010-2011 | MAR | STAIRCASE CABIN | | | 0 | | |
| | | CR TO R/C BUILDING TRIMURTI, - REMOVING & | 0.000 | 0.000 | | In Progress | |
| 2010-2011 | MAR | REPLACING DAMAGED GI PIPES. | | | 0 | | |
| 2010-2011 | MAR | REPAIRS TO OH WATER STORAGE TANK | 0.000 | 0.000 | 0 | In Progress | |
| | | CR TO R/C BLDG OMKAR REPAIRS TO COMMON | 0.000 | 0.000 | | In Progress | |
| 2010-2011 | MAR | PASSAGE & HEAD ROOM | | | 0 | | |
| 2010 2011 | | CLEANING & WASHING OF UG & OH TANK OF R/C BLDGS UNDER D-1 | 0.000 | 0.000 | 0 | In Progress | |
| 2010-2011 | IVIAK | | 0.000 | 0.000 | 0 | In Progress | |
| 2010-2011 | MAR | CR TO R/C BUILDING TRIMURTI, - REPAIRS TO PVC PIPES & GI PIPES. | 0.000 | 0.000 | 0 | in rogress | |
| 2010 2011 | | CLEANING & WASHING OF UG & OH TANK OF R/C | 0.000 | 0.000 | 0 | In Progress | |
| 2010-2011 | MAR | BLDGS UNDER D-1 | | | 0 | | |
| | | SWEEPING & CLEANING WORK OF ALL TENEMENTS | 0.000 | 0.540 | | Completed | |
| | | & SHOPS UNDER D-1 WARD (721 t/S) 01.12.2010 TO | | | | | |
| 2010-2011 | MAR | 28.02.2011 | | | 0.54 | | |
| | | PROVIDING ANTI-TERMITE TREATMENT TO | 0.000 | 0.000 | | In Progress | |
| 2010-2011 | MAR | PARISHRAM BLDG | | | 0 | | |
| | | CR TO R/C BUILDING HARI-OM IN D-1 DIV REPAIRS | 0.000 | 0.000 | | In Progress | |
| 2010-2011 | MAR | TO OH WATER TANK | | | 0 | | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| | | CR TO R/C BUILDING NIRDHAR IN D-1 DIV REMOVING CHOCKAGES FROM DRAINAGE LINE & | 0.180 | 0.000 | | Completed | |
| 2010-2011 | MAR | REPLACING PVC PIPES | 0.020 | 0.000 | 0.18 | | |
| 2010-2011 | MAR | CR TO R/C BUILDING TRIMURTI, - REPAIRS HOUSE | 0.620 | 0.000 | 0.62 | Completed | |
| | | | 0.620 | 0.000 | | Completed | |
| 2010-2011 | MAR | CR TO R/C BUILDING HARI-OM IN D-1 DIV REPAIRS TO UG WATER TANK & ROOM CEILING | | | 0.62 | | |
| 2010-2011 | MAR | CR TO R/C BUILDING TRIMURTI IN D-1 DIV P/A BITUMEN TO THE TERRACE, HEAD ROOM, REPAIRS TO PVC PIPES AND TREE CUTTING | 0.280 | 0.000 | 0.28 | Completed | |
| 2010-2011 | MAR | SR WORK OF PROVIDING WATER PROOFING TREATMENT TO TERRACE OF TRIMURTI BLDG UNDER D-1 WARD | 0.000 | 0.000 | 0 | In Progress | |
| 2010-2011 | | SR WORK OF EXTERNAL & INTERNAL, PLASTER AND PAINTING TO TRIMURTI BLDG UNDER D-1 WARD | 0.000 | 0.000 | 0 | In Progress | |
| 2010-2011 | MAR | SR WORK OF EXTERNAL & INTERNAL, PLASTER AND PAINTING TO PARISHRAM BLDG UNDER D-1 WARD | 0.000 | 0.000 | 0 | In Progress | |
| 2010-2011 | MAR | SR WORK OF EXTERNAL & INTERNAL, PLASTER AND PAINTING TO NIRDHAR BLDG UNDER D-1 WARD | 0.000 | 0.000 | 0 | In Progress | |
| 2010-2011 | MAR | SR WORK OF EXTERNAL & INTERNAL, PLASTER AND PAINTING TO KUSH BLDG UNDER D-1 WARD | 0.000 | 0.000 | 0 | In Progress | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|------------------------|-------|--|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| 2010-2011 | MAR | CR TO R/C BUILDING JANKI NIWAS IN D-1 DIV REPAIRS TO UG & OH TANK AS PER PCO'S NOTICE | 0.000 | 0.000 | 0 | In Progress | |
| 2010-2011 | MAR | CR TO R/C BUILDING HARI-OM IN D-1 DIV REPAIRS TO UG & OH TANK AS PER PCO'S NOTICE | 0.000 | 0.000 | 0 | In Progress | |
| 2010-2011 | MAR | CR TO R/C BUILDING SHATRUGHNA IN D-1 DIV REPAIRS TO UG & OH TANK AS PER PCO'S NOTICE | 0.000 | 0.000 | 0 | In Progress | |
| 2010-2011 | MAR | SR WORK OF INTERNAL PLASTER AND PAINTING TO RAM BLDG UNDER D-1 WARD | 0.000 | 0.000 | 0 | In Progress | |
| 2010-2011 | MAR | CR TO R/C BUILDING SIDDHIVIHAR IN D-1 DIV REPAIRS TO UG & OH TANK AS PER PCO'S NOTICE | 0.000 | 0.000 | 0 | In Progress | |
| 2010-2011 | MAR | CR TO R/C BUILDING RAM IN D-1 DIV REPAIRS TO UG & OH TANK AS PER PCO'S NOTICE | 0.000 | 0.000 | 0 | In Progress | |
| 2010-2011 | | CR TO R/C BUILDING KUSH IN D-1 DIV REPAIRS TO IMPROVEMENT DRAINAGE SYSTEM | 0.000 | 0.620 | 0.62 | Completed | |
| | | SWEEPING & CLEANING WORK OF ALL TENEMENTS & SHOPS UNDER D-1 WARD (687 t/S) 01.03.2011 TO | 0.000 | 0.000 | 0.02 | In Progress | |
| 2010-2011 2010-2011 | | 31.05.2011 CR TO R/C BLDG. LUV IN D 1 DIVN- REPAIRS TO UG & HO TANK AS PER PCO' NOTICE. | | 0.000 | 0 | In Progress | |
| 2010-2011 | MAR | SR TO R/C BLDG. KNOWN AS SHATRUGHNA IN D-1 DIVN- REPAIRS TO WATER PROOFING TERRACE & O H WATER TANK. | 0.000 | 0.000 | 0 | In Progress | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| | | | 0.000 | 0.000 | | In Progress | |
| | | CR TO RC BLDG. KNOWN AS JAYVIJAY IN D-1 DIVN | | | | | |
| 2010-2011 | MAR | REPAIRS TO U G & O H TANK AS PER PCO'S NOTICE. | 0.000 | 0.000 | 0 | la Das susses | |
| | | CR TO RC BLDG. KNOWN AS JANKINIWAS IN D-1 | 0.000 | 0.000 | | In Progress | |
| | | DIVN REPAIRS TO U G & O H TANK AS PER PCO'S | | | | | |
| 2010-2011 | | NOTICE. | | | 0 | | |
| 2010-2011 | MAR | R/C Bldg Maniyar, B-1, Tardeo Road | 0.61 | 0 | 0.61 | completed | |
| | | R/C Bldg known as "Guruchaya" at 1st Parsiwada, | | | | | |
| 2010-2011 | MAR | Replacing of sewerage lines D-2 Division. | 0.61 | 0 | 0.61 | completed | |
| 2010 2011 | | R/C Bldg known as "Guruchaya" at 1st Parsiwada, | 0.01 | | | | |
| 2010-2011 | MAR | construction of compound wall D-2 Division. | 0.61 | 0 | 0.61 | completed | |
| | | Cleaning of UGT & OHT at various Reconstruction Bldg | | | | | |
| 2010 2011 | | 50T/s (Chirag, Kanchwala, Bhagyshree, Guruchhaya) (| 0.05 | 0 | 0.05 | | |
| 2010-2011 | MAR | Rate List) Cleaning of UGT & OHT at various Reconstruction Bldg | 0.05 | 0 | 0.05 | completed | |
| 2010 2011 | | 50T/s (Neelkamal & Indraprastha) (Rate List) | 0.02 | 0 | 0.03 | completed | |
| 2010-2011 | IVIAR | Cleaning of UGT & OHT at various Reconstruction Bldg | 0.02 | 0 | 0.02 | completed | |
| 2010-2011 | MAR | 150T/s (Geetanjali) (Rate List) | 0.02 | 0 | 0.02 | completed | |
| 2010-2011 | IVIAN | Cleaning of UGT & OHT at various Reconstruction Bldg | 0.02 | 0 | 0.02 | completed | |
| 2010-2011 | MAR | 200 T/s (Rate List) | 0.05 | 0 | 0.05 | completed | |
| 2010-2011 | | Cleaning of UGT & OHT at various Reconstruction Bldg | 0.00 | Ŭ | 0.03 | completed | |
| 2010-2011 | MAR | 50 T/s (Rate List) | 0.11 | 0 | 0.11 | completed | |
| 2010 2011 | | Cleaning of UGT & OHT at various Reconstruction Bldg | | | 0.11 | | |
| 2010-2011 | MAR | 100 T/s (Rate List) | 0.05 | 0 | 0.05 | completed | |
| | | Cleaning of UGT & OHT at various Reconstruction Bldg | | | | | |
| 2010-2011 | MAR | 150T/s (Rate List) | 0.06 | 0 | 0.06 | completed | |
| | | Cleaning of UGT & OHT at various Reconstruction Bldg | | | | | |
| 2010-2011 | MAR | 100 T/s (Rate List) | 0.05 | 0 | 0.05 | completed | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|-----------------------|---------|
| | | C.R. Repairs to the T/s in Maniyar A-1, Tardeo Road. | 0.00 | | 0.00 | | |
| 2010-2011 | MAR | (Rate List) | 0.66 | 0 | 0.66 | completed | |
| | | C.R. to R/C Bldg Kaveri, Rachana 1, 2 in D-2 ward | | | | | |
| | | Replacement of damaged and decoverd W.C.Bath door | | | | | |
| 2010 2011 | | Frame shutter and P.V.C. pipes repairs window /door frame and shutter. | 0.24 | 0 | 0.24 | and the second second | |
| 2010-2011 | IVIAK | C.R. to R/c building Kaveri Rachana-1 in D-2 ward | 0.24 | 0 | 0.24 | completed | |
| 2010 2011 | | Repairs to tenement ceiling plaster | 0.25 | 0 | 0.25 | completed. | |
| 2010-2011 | IVIAK | C.R. to R/c building Maniyar C-1 C-2 repairs to inspection | 0.25 | 0 | 0.25 | completed | |
| 2010-2011 | | chembers in D-2 ward | 0.24 | 0 | 0.24 | completed | |
| 2010-2011 | | C.R. to R.C Bldg Sai Prasad in D-2 ward repairs to the | 0.24 | <u> </u> | 0.24 | completed | |
| 2010-2011 | MAR | part terrace providing water proofing | 0.24 | 0 | 0.24 | completed | |
| 2010-2011 | | Sweeping Cleaning work of all tenements and shop area under "D" ward (525) T/s (1st Sept to 30th Nov) | 0.40 | 0 | 0.4 | completed | |
| 2010-2011 | MAR | C.R. to R/C Bldg Kaveri, Krishna, Koyana in D-2 ward. Repairs to Room No. 201, 408, 501,403 ceiling wall plaster etc. | 0.56 | 0 | 0.56 | completed | |
| 2010-2011 | MAR | S.R. to R/C Bldg known as 1 Naushir Bharucha Marg, Grant Road, New Chikalwadi A.R.P.Bldg "D" ward. | 6.24 | 0 | 6.24 | completed | |
| 2010-2011 | MAR | C.R. to R/c Bldg known as Sai Prasad in D-2 ward. Repairs to ceiling to T/s No.301 passage opp. Room no.314 | 0.15 | 0 | 0.15 | completed | |
| 2010-2011 | MAR | S.R. to R/C Bldg known as Maniyar -1at Tardeo road D-2 Divn. Providing waterproofing treatment at terrace. | 4.95 | 0 | 4.95 | completed | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| | | S.R. to R/C work to building known as at Rajani Mahal, | | | | | |
| 2010-2011 | MAR | Tardeo Road | 7.90 | 0 | 7.9 | completed | |
| 2010-2011 | MAR | Sweeping Cleaning work of all tenements and shop area under "D" ward (537) T/s | 0.44 | 0 | 0.44 | completed | |
| 2010 2011 | | Sweeping Cleaning work of all tenements and shop area | | U U | | completed | |
| 2010-2011 | MAR | under "D" ward (770) T/s | 0.44 | 0 | 0.44 | completed | |
| | | Sweeping Cleaning work of all tenements and shop area | | | | | |
| 2010-2011 | MAR | under "D" ward (365) T/s | 0.44 | 0 | 0.44 | completed | |
| 2010-2011 | MAR | S.R. to R/C Building Sankalp Siddhi in D-2 Divn. | 2.62 | 0 | 2.62 | completed | |
| | | S.R. to R.C. work, New Chikhalwadi, Naushir Bharucha | | | | | |
| 2010-2011 | MAR | Marg, Opp. Bldg Rachana 4 cleaning | 5.74 | 0 | 5.74 | completed | |
| | | C.R. to R/c bldg Sankalpa Siddhi, Neel Kamal | | | | | |
| | | Replacement P.V.C. pipe/ cleanning of Drainage line | | | | | |
| 2010-2011 | MAR | work. | 0.20 | 0 | 0.2 | completed | |
| | | C.R. to R/c Bldg Koyan, Sai Prasad, Providing PVC pipe | | | | | |
| 2010-2011 | MAR | removing chockup and trees cutting. | 0.21 | 0 | 0.21 | completed | |
| | | C.R. to R.C. Bldg Geetanjali "A" wing providing shahabad | | | | | |
| 2010-2011 | MAR | Ladi House gully | 0.61 | 0 | 0.61 | completed | |
| | | C.R. to R/C Bldg Sai Prasad Removing loose, concrete | | | | | |
| 2010-2011 | MAR | plaster of column, beam wall, | 0.18 | 0 | 0.18 | completed | |
| | | C.R. to R/C Bldg, Rachana -3, Replacement of G.I.Pipe, | | | | | |
| 2010-2011 | MAR | Repairs to Nahani | 0.33 | 0 | 0.33 | completed | |
| | | C.R. to R/c to providing antiternite treatment to R/c Bldg | | | | | |
| 2010-2011 | MAR | known as Rajani Mahal in D-ward | 0.58 | 0 | 0.58 | completed | |
| | | S.R. to R.C. Bldg at Rajani Mahal, Tardeo Road, Repairs | | | | | |
| 2010-2011 | MAR | to over head tank | 1.60 | 0 | 1.6 | completed | |
| | | C.R. to R/c Bldg Geetanjali "A" wing, cleanning of sewer | | | | | |
| 2010-2011 | MAR | line, Replacement of P.V.C. pipe | 0.24 | 0 | 0.24 | completed | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| | | C.R. to R/c Building Geetanjali, "B" wing Repairs to | | | | | |
| 2010-2011 | MAR | Inspection chambers and Trees cutting | 0.24 | 0 | 0.24 | completed | |
| 2010-2011 | MAR | C.R. to R/C Bldg, New Chikhalwadi common work for cleanning of draninage line | 0.33 | 0 | 0.33 | completed | |
| 2010-2011 | MAR | C.R. to R/c Bldg, Rajani Mahal, Providing and fixing collaps side gate grill on floor near control room, Repairs to Room No.203,204 & Replacement of PVC-Pipe | 0.49 | 0 | 0.49 | completed | |
| 2010-2011 | MAR | C.R. to R/c Bldg, Rachana -4, Repairs to Inspection chamber and Trees cutting | 0.35 | 0 | 0.35 | completed | |
| 2010-2011 | | C.R. to R/c Bldg, Koyana Bldg, Attending Leakages by providing leak injections treatment replacement of PVC Pipe | 0.18 | | 0.18 | completed | |
| 2010-2011 | MAR | Attending leakages from W.C. & bath of Ambedkar Sadan & Shivratna | 0.57 | 0.00 | 0.57 | completed | |
| 2010-2011 | MAR | bldg. No. 1, Ambedkar Sadan, Vaishnav Sadan, Mahatma Phule Sadan, Shivkripa, Shivratna, Vishranti | 0.52 | 0.00 | 0.52 | completed | |
| 2010-2011 | MAR | bldg. No. 2, Khoja Chawl, Safalya No. 1 & 2, Shivsmruti, Saidham | 0.57 | 0.00 | 0.5733 | completed | |
| 2010-2011 | MAR | Bldg. No. 3, Devgiri Chatrapati Sahu Sadan, Rajgad Panchaganga 1 to 5 | 0.55 | 0.00 | 0.553 | completed | |
| 2010-2011 | MAR | bldg. No. 3, Devgiri, Chatrapati Shahusadan, Rajgad, Panchganga 1 to 5 | 0.55 | 0.00 | 0.55 | completed | |
| 2010-2011 | MAR | bldg. No. 4, Bajrang Krupa,Krishna Niwas,Omsai Sadan,Saisagar,Mahala.,Tapovan ABC,Bhagirath,Ratnasin | 0.62 | 0.00 | 0.62 | completed | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| 2010-2011 | MAR | bldg. No. 5, Swamisadan, Sarang, Durganiwas, Trishul No. 1 & 2, Kokanvaibhav, Jaibhavani Sadan | 0.56 | 0.00 | 0.56 | completed | |
| 2010-2011 | MAR | bldg. no. 6, Yugarambha, Ganeshniketan,Adwait Laxmisadan, Shreeram Sadan, Saisharddha,Vishwajyoti | 0.55 | 0.00 | 0.55 | completed | |
| 2010-2011 | MAR | bldg. No. 7,Shivraj Bhavan 1 & 2, StyamShivamSundram, Kabirashram,Vinayaksadan, Ganeshkripa | 0.51 | 0.00 | 0.51 | completed | |
| 2010-2011 | MAR | Bldg. No. Pimpleshwar Krupa | 8.64 | 0.00 | 8.64 | In Progress | |
| 2010-2011 | MAR | bldg. No.1, Ambedkarsadan, Vaishnavsadan, Mahatmaphule sadan, Shivkrupa,Shivrama,Vinayaksadan | 0.52 | 0.00 | 0.5233 | completed | |
| 2010-2011 | MAR | bldg. No.8, Bramhasiddhi, Ganeshprabha,Datta Prasad, Siddhiprabha, Raowadi, Shalimar, Sagar, Gurukru | 0.57 | 0.00 | 0.57 | completed | |
| 2010-2011 | MAR | bldg.No. 4, Bajrangkrupa, Krishnaniwas, Omsaisadan, Saisagar, Mahalaxmidarshan, Tapovan ABC,Bhagirat | 0.62 | 0.00 | 0.6224 | completed | |
| 2010-2011 | MAR | Bldg.No. 5, Swamisadan, Sarang, Durganiwas, Trishul No. 1 & 2, Kokan Vaibhav, Jai Bhavansadan | 0.56 | 0.00 | 0.5639 | completed | |
| 2010-2011 | MAR | Bldg.No.6, Yugaranbha,Ganeshniketan,Adwait,Laxmisadan,Shreera msadan,Saishradha,Vishwayotisadan | 0.55 | 0.00 | 0.5475 | completed | |
| 2010-2011 | MAR | Bldg.No.7,Shivraj Bhavan 1 & 2,Satyam,Shivam,Sundaram,Kabirashram,Vinayaksadan, Ganeshkrupa | 0.51 | 0.00 | 0.514 | completed | |



| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| 2010-2011 | . MAR | Bldg.No.8, Bramhasiddhi,Ganeshprabha,Dattaprasad,Siddhiprabha,R aowadishalimar,Sagardarshan,Gurukrupa | 0.57 | 0.00 | 0.5717 | completed | |
| 2010-2011 | MAR | C.R. to providing ceiling plaster to siporex slab in ShivKrupa | 0.61 | 0.00 | 0.61 | completed | |
| 2010-2011 | MAR | C.R. to providing ceilings plaster to (Siporex slab) of Shivraj Bhuvan No. 2 | 0.62 | 0.00 | 0.62 | completed | |
| 2010-2011 | MAR | Cleaning of U.G. & O.H. water tank | 0.62 | 0.00 | 0.62186 | completed | |
| 2010-2011 | MAR | Compliance of PCO Nokces to bring the OHT, UGST of Mosquitoproof Conditions | 0.61 | 0.00 | 0.61118 | completed | |
| 2010-2011 | MAR | Compliance of R.C.O. Notices to being te OHT/ UGST of mosquito proof conditions | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | CR tgo providing ceiling plaster to siporex slab Shivraj Bhuvan No. 1 | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | CR to RC bldg. Siddhi Sadan, Reprs. to damage flooring | 0.62 | 0.00 | 0.62 | completed | |
| 2010-2011 | MAR | CR to RC bldg. Suyash, Elphi. Rd (Attending leakage of OH water tank | 0.53 | 0.00 | 0.53 | completed | |
| 2010-2011 | MAR | Deterioted frame/shutter of draw,windows & colapsible gates | 0.64 | 0.00 | 0.64 | completed | |
| 2010-2011 | MAR | Dilapidated portion & repairs to peeled off portion of compound wall of Sai Sagar | 0.63 | 0.00 | 0.63 | completed | |
| 2010-2011 | MAR | Improvement in drainage system of Devgiri | 0.39 | 0.00 | 0.39 | completed | |
| 2010-2011 | MAR | Improvement of drainage system of Sai Sagar | 0.56 | 0.00 | 0.56 | completed | |
| 2010-2011 | MAR | Improvement to drainage system of Trishul 1 & 2 | 0.47 | 0.00 | 0.47118 | completed | |
| 2010-2011 | MAR | Krshnaniwas,Omsaisadan,Ganeshkrupa,Suyash,Nalanda, Shantiniwas,Siddhisadan | 0.61 | 0.00 | 0.61 | completed | |
| 2010-2011 | MAR | Leakage of O.H. Water tank, of Ganesh Niketan | 8.73 | 0.00 | 8.73 | completed | |



| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| 2010-2011 | MAR | Leakages from WC & bath of Pimpleshwar Krupa | 0.31 | 0.00 | 0.312 | completed | |
| 2010-2011 | . MAR | Pepalcement of leaking/ carraded G.I. pipe line feeding to Krishna Niwas | 0.34 | 0.00 | 0.34 | completed | |
| 2010-2011 | MAR | Plastering & Painting of Chatrapati Shahu Sadan | 0.62 | 0.00 | 0.62 | completed | |
| 2010-2011 | MAR | Plastering & Painting of Datta Krupa | 0.45 | 0.00 | 0.45 | completed | |
| 2010-2011 | MAR | Plastering & Painting of Durga Niwas | 0.33 | 0.00 | 0.33 | completed | |
| 2010-2011 | MAR | Plastering & Painting of Ganesh Krupa | 0.24 | 0.00 | 0.23757 | completed | |
| 2010-2011 | MAR | Plastering & Painting of Jai Bhavani Sadan | 8.85 | 0.00 | 8.85 | completed | |
| 2010-2011 | MAR | Plastering & Painting of Rajgad | 5.65 | 0.00 | 5.65 | In Progress | |
| 2010-2011 | MAR | Plastering & Painting of Yugarambha | 7.63 | 0.00 | 7.63 | completed | |
| 2010-2011 | MAR | Plastering & Painting | 11.25 | 0.00 | 11.25 | completed | |
| 2010-2011 | MAR | Plastering & Painting | 0.00 | 9.13 | 9.13 | completed | |
| 2010-2011 | MAR | Providing ceiling plaster to various of Sanjivani Prasad, Subhshank | 6.78 | 0.00 | 6.78 | completed | |
| 2010-2011 | MAR | Providing G.I. pipe railing on terrace of Trishul No. 1 | 4.83 | 0.00 | 4.83 | completed | |
| 2010-2011 | MAR | Providing IPS to UGST & repairs to shop of Stayam Shivam Sundaram | 8.00 | 0.00 | 8 | completed | |
| 2010-2011 | MAR | Providing plastering & painting of Sanjivani Prasad | 7.11 | 0.00 | 7.11 | In Progress | |
| 2010-2011 | . MAR | Providing plinth prolection to North side and around UGST of vinayak Sadan. | 0.61 | 0.00 | 0.61452 | completed | |
| 2010-2011 | MAR | Providing W/P to terrace & OHT of Sanjivani Prasad | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Providing waterproofing to terrace & O.H. Tank of Tapovan A.B.C. | 0.55 | 0.00 | 0.55 | completed | |
| 2010-2011 | MAR | Providing waterproofing treatment to terrace & OH Tank Vishranti | 0.25 | 0.00 | 0.2494 | completed | |
| 2010-2011 | MAR | Removing loose ceiling plaster of common passage of Trishul No. 2 | 5.19 | 0.00 | 5.19 | completed | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| 2010-2011 | MAR | Removing loose/ hollow ceiling plaster cover of soffits of Trishul No. 2 | 0.48 | 0.00 | 0.4791 | completed | |
| 2010-2011 | MAR | Rep.to loose ceiling of Panchganga 2. | 2.84 | 0.00 | 2.84 | completed | |
| 2010-2011 | MAR | Rep.to loose ceiling of Panchganga 3 | 10.63 | 0.00 | 10.63 | In Progress | |
| 2010-2011 | MAR | Rep.to loose ceiling of Panchganga 4 | 3.18 | 0.00 | 3.18 | completed | |
| 2010-2011 | MAR | Rep.to loose ceiling of Panchganga 5 | 0.36 | 0.00 | 0.36 | completed | |
| 2010-2011 | MAR | Rep.to PVC pipes of Jai Bhavani Sadan | 0.62 | 0.00 | 0.62 | completed | |
| 2010-2011 | MAR | Repair & painting to staircase & common passage of Panchganga No. 1 | 0.57 | 0.00 | 0.57 | completed | |
| 2010-2011 | MAR | Repairing of underground tank of Safalya | 0.62 | 0.00 | 0.62 | completed | |
| 2010-2011 | MAR | Repairs to ceiling of rooms C.R. to Shivsmurti | 0.62 | 0.00 | 0.62 | completed | |
| 2010-2011 | MAR | Repairs to Ceilingof Devgiri | 0.58 | 0.00 | 0.58 | completed | |
| 2010-2011 | MAR | Repairs to common Verandah of Vishranti | 0.56 | 0.00 | 0.56 | completed | |
| 2010-2011 | MAR | Repairs to drainage & plints protecting of Dattakrupa B wing | 0.62 | 0.00 | 0.62 | completed | |
| 2010-2011 | MAR | Repairs to WC`s & bath`s in Pimpleshwar Krupa | 0.18 | 0.00 | 0.1771 | completed | |
| 2010-2011 | MAR | Replacement of carraded/ outdatedd G.I. pipe line on terrace of Tapovan | 0.57 | 0.00 | 0.57 | completed | |
| 2010-2011 | MAR | Replacement of corroded/ leaking/ outdated G.I.pipe & gate valve of Mahatma Phule Sadan & Vaishav Sa | 1.94 | 0.00 | 1.94 | completed | |
| 2010-2011 | MAR | Replacement of corroded/ outdated leaking G.I. pipe/ fitting of Satyam Shivam Sundaram, Advait & Sid | 0.62 | 0.00 | 0.62 | completed | |
| 2010-2011 | MAR | Replacement of damaged/ carraded G.I. pipe line on terrace of Om sai Sadan | 0.65 | 0.00 | 0.65 | completed | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|--|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| 2010-2011 | MAR | Replacement of damaged/ corroded/ leaking downtake G.I pipe/fittings & wheeled stoptap Trishul No.2 | 0.62 | 0.00 | 0.62409 | completed | |
| 2010-2011 | MAR | Replacement of damaged/ corroded/ leaking downtake G.I. pipe/ fittings of terrace of Trishul No. 2 | 0.25 | 0.00 | 0.24969 | completed | |
| 2010-2011 | MAR | Replacement of deterioated frame, shutters of window of 56, corrol road, Shivraj Bhavan No. 2 | 0.25 | 0.00 | 0.24818 | completed | |
| 2010-2011 | | replacement of leacking/ corroded G.I. pipe/ fitings of 56 carrol road, Shivraj Bhavan No. 2 | 0.25 | 0.00 | 0.24796 | completed | |
| 2010-2011 | MAR | Replacement of leaking/ corroded G.I. pipe fitting of 128- 130 Safalya No. 2 | 0.55 | 0.00 | 0.55407 | completed | |
| 2010-2011 | MAR | Replacement of leaking/ corroded G.I. pipe/ fittings of Trishul No. 2 & Swami Sadan | 0.64 | 0.00 | 0.64 | completed | |
| 2010-2011 | MAR | Replacement of outdated wheeled stop tap of Tapovan A & B | 0.61 | 0.00 | 0.60731 | completed | |
| 2010-2011 | MAR | Replacing A.C. Gas pipe with PVL pipe & removing/refixing exting PVL pipe of Vishranti | 0.24 | 0.00 | 0.24223 | completed | |
| 2010-2011 | MAR | Replacing damaged & Rep.loose ceiling of Panchganga 1 | 0.51 | 0.00 | 0.50843 | completed | |
| 2010-2011 | MAR | Replacing decoyed wooden weather shed & Rep to existing weather of Jai Bhavani Sadan | 0.62 | 0.00 | 0.61621 | completed | |
| 2010-2011 | MAR | Replc.Damaged PVC pipes of Ambedkar Sadan,ShivajiBhavan1 & 2,LaxmiSadan,SiddhiSadan,Suyash,ShivKripa | 0.25 | 0.00 | 0.24568 | completed | |
| 2010-2011 | MAR | Reps.of Damaged/deeayed pumproom,meterroom of Panchganga p/f welded wash to pumprooriwindows | 0.56 | 0.00 | 0.56 | completed | |



| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| 2010-2011 | MAR | S & C of group No. 5, Swami Sadan, Sarang, Durga Niwas, Trishul No. 1 & 2 Kokan Vaibhav, Jai Bhavni | 0.61 | 0.00 | 0.61 | completed | |
| 2010-2011 | MAR | S & C of group No. 6 Yugarambha, Ganesh Niketan, Adwait, LaxmiSadan, Shree Ram Sadan, Sai Shradha | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | S & C of group No. 7, Satyam Shivam Sundaram, Kabirashram, Vinayak Sadan, Ganesh Krupa | 0.61 | 0.00 | 0.61 | completed | |
| 2010-2011 | MAR | S C of Group No. 2, Khoja Cahwl, Safalya No. 1 & 2, Shivsmruti, Saidham | 0.61 | 0.00 | 0.61 | completed | |
| 2010-2011 | MAR | Special repairs to 100C, Bori Chawl Mahalaxmi Darshan | 0.60 | 0.00 | 0.6 | completed | |
| 2010-2011 | MAR | Tree cutting and leakage | 0.55 | 0.00 | 0.55 | completed | |
| 2010-2011 | MAR | WC & bath of Pimpleshwar A wing | 0.55 | 0.00 | 0.55 | completed | |
| 2010-2011 | MAR | C.R. to R/C bldg. Suyash, Elphinstone Road, repairs to IPS flooring | 0.57 | 0.00 | 0.57 | completed | |
| 2010-2011 | MAR | C.R. to R/C bldg. Siddhi Sadan, Fitwala Road, repairs to damage flooring (Front side) | 4.51 | 0.00 | 4.51 | completed | |
| 2010-2011 | MAR | C.R. to R/C bldg. Om Sai Sadan, Parsiwada, attending leakage of O.H. water tank | 0.54 | 0.00 | 0.53863 | completed | |
| 2010-2011 | MAR | C.R. to R/C bldg. Trishul No. 2, repairs to peeled off enternal cement plaster of common toilet bathroom | 0.62 | 0.00 | 0.62 | completed | |
| 2010-2011 | MAR | C.R. to R/C bldg. Ambedkar Sadan, repairs to damage GI Pipe | 0.25 | 0.00 | 0.25 | completed | |
| 2010-2011 | MAR | S & C of R/C building Bramhasidhi, Ganeshprabha, Dattprasad, Sukhshanti, Dattkripa, Siddhisai. | 0.62 | 0.00 | 0.62 | completed | |
| 2010-2011 | MAR | S & C of R/C building Shivraj Bhavan 1&2, Satyam Shivam Sundaram, Kabirashram, Ganesh kripa(Std.Mill Lane), | 0.57 | 0.00 | 0.57 | completed | |



| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| 2010-2011 | MAR | S & C of R/C building Safalya 1& 2, Saidham | 0.50 | 0.00 | 0.5 | completed | |
| 2010-2011 | MAR | S & C of R/C building Bajrang Kripa, saisagar, Mahalaxmi Darshan, Tapovan A B C, Bhagirath, Ratnasidhu, Shamsunder Sadan. | 0.25 | 0.00 | 0.25 | completed | |
| 2010-2011 | MAR | S & C of R/C building Yugarambha, Ganesh Niketan, Adwait, Laxmi Sadan, Shree Ram Sadan, Sai Shradha, Vishwajyoti Sadan. | 12.14 | 0.00 | 12.14 | completed | |
| 2010-2011 | MAR | S & C of R/C building Swami Sadan, Sarang, Durga Niwas, Trishul 1&2, Kokan Vaibhav, Jai Bhavani Sadan. | 7.41 | 0.00 | 7.41 | completed | |
| 2010-2011 | MAR | C.R. to R/C Bldg. Dattkripa A wing. Rep to Drainage & Plinth Protection. | 0.59 | 0.00 | 0.59 | completed | |
| 2010-2011 | MAR | Replacement of corroded / leaking G.I. Pipe fittings of R/C bldg. Adwait. | 0.59 | 0.00 | 0.59 | completed | |
| 2010-2011 | MAR | Replacement of corroded / leaking /outdated G.I. Pipe fittings of R/C bldg. Bhagirath | 0.31 | 0.00 | 0.31 | completed | |
| 2010-2011 | MAR | Replacement of corroded / leaking /outdated G.I. Pipe fittings of R/C bldg. Yugarambha, planet Mill Lane. | 0.31 | 0.00 | 0.31 | completed | |
| 2010-2011 | MAR | Replacement of corroded / leaking /outdated G.I. Pipe fittings of R/C bldg. Safalya No.2. | 0.29 | 0.00 | 0.29 | completed | |
| 2010-2011 | MAR | Replacement of corroded / leaking /outdated G.I. Pipe fittings of R/C bldg. Trishul No.2. & Swami Sadan. Sitaram Jadhav Marg. | 0.52 | 0.00 | 0.52 | completed | |
| 2010-2011 | MAR | Replacement of corroded / leaking /outdated G.I. Pipe fittings of R/C bldg. Bhagirath. | 0.52 | 0.00 | 0.52 | completed | |
| 2010-2011 | MAR | Rep. to P.V.C.pipes of R/C. Building Jai Bhavani Sadan. | 0.25 | 0.00 | 0.25 | completed | |



| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| 2010-2011 | MAR | Replacement of corroded / leaking /outdated G.I. Pipe fittings of R/C bldg. Satyam Shivam Sundaram | 0.65 | 0.00 | 0.65 | completed | |
| 2010-2011 | MAR | Replacement of corroded / leaking /outdated G.I. Pipe fittings of R/C bldg. Bajrang Kripa | 0.25 | 0.00 | 0.25 | completed | |
| 2010-2011 | MAR | Replacement damaged / decoyed frame / shuter and fixing welded of pupm house of R/C. Bldg.Sarang | 0.62 | 0.00 | 0.62 | completed | |
| 2010-2011 | MAR | Replacement of damaged door shuter of R/C.bldg.Sarang | 0.65 | 0.00 | 0.65 | completed | |
| 2010-2011 | MAR | Rep.to ceiling of R/C.bldg.Devgiri | 0.63 | 0.00 | 0.63 | completed | |
| 2010-2011 | MAR | Replacement of corroded / leaking /outdated G.I. Pipe fittings of R/C bldg. Safalya | 0.64 | 0.00 | 0.64 | completed | |
| 2010-2011 | MAR | Replacement of corroded / leaking /outdated G.I. Pipe fittings of R/C bldg. Shree Ram Sadan | 0.54 | 0.00 | 0.54 | completed | |
| 2010-2011 | MAR | Rep.to pump house of R/C. bldg.Tapovan | 0.25 | 0.00 | 0.25 | completed | |
| 2010-2011 | MAR | Rep.to meter room of R/C. bldg.Tapovan | 0.64 | 0.00 | 0.64 | completed | |
| 2010-2011 | MAR | S & C of R/C.bldg.Safalya 1 & 2 | 0.26 | 0.00 | 0.26 | completed | |
| 2010-2011 | MAR | Replacement of corroded / leaking /outdated G.I. Pipe fittings of R/C bldg. Kabirashram | 0.26 | 0.00 | 0.26 | completed | |
| 2010-2011 | MAR | S & C of R/C.bldg.Shivraj Bhavan 1&2, Satyam Shivam Sundaram, Ganesh Kripa, Siddivinayak Kripa | 0.44 | 0.00 | 0.44 | completed | |
| 2010-2011 | MAR | S & C of R/C.bldg.Bramhasidhi, Ganesh Prabha, Dattprasad, Siddhiprabha, Sanjivani Parasad, Sukh shanti, Dattkripa, siddhisai. | 0.64 | 0.00 | 0.64 | completed | |
| 2010-2011 | MAR | Replacement damaged / decoyed frame / shuter of pump room and meter room of R/C. Bldg.Tapovan | 0.60 | 0.00 | 0.6 | completed | |



| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| 2010-2011 | l MAR | S & C of R/C.bldg.Swami Sadan, Sarang, Durga Niwas, Trishul 1 & 2, Kokan Vaibhav, Jai Bhavani | 0.66 | 0.00 | 0.66 | completed | |
| 2010-2011 | LMAR | S & C of R/C.bldg.Bajarang Krupa, Sai Sagar, Mahalaxmi Darshan, Tapovan, Bhagirath, Rantna Sindhu, Shyam Sundar Sadan | 0.51 | 0.00 | 0.51 | completed | |
| 2010-2011 | L MAR | S & C of R/C.bldg.Yugaranbh, Ganesh Niketan, Adwait, Laxmi Sadan, Shriram Sadan, Sai Shraddha, Vishwajyoti Sadan | 0.61 | 0.00 | 0.61 | completed | |
| 2010-2011 | MAR | Replacement of corroded / leaking /outdated G.I. Pipe fittings of R/C bldg. Sai Shraddha | 0.57 | 0.00 | 0.57 | completed | |
| 2010-2011 | L MAR | Replacement of corroded / leaking /outdated G.I. Pipe fittings of R/C bldg. Sai Dham | 0.44 | 0.00 | 0.44 | completed | |
| 2010-2011 | LMAR | Replacement damaged / decoyed frame / shuter and fixing welded of pupm house of R/C. Bldg.Sarang | 0.48 | 0.00 | 0.48 | completed | |
| 2010-2011 | L MAR | S.R.to R/C.bldg.Ambedkar Sadan. Plastering & Painting | 0.28 | 0.00 | 0.28 | completed | |
| 2010-2011 | l MAR | S.R.to R/C.bldg.Krishna Niwas. Plastering & Painting | 0.54 | 0.00 | 0.54 | completed | |
| 2010-2011 | l MAR | S & C of R/C.bldg.Devgiri, Chatrapati Shahu Sadan, Rajgad, Panchaganga, Vinayak Sadan. | 0.32 | 0.00 | 0.32 | completed | |
| 2010-2011 | l MAR | S & C of R/C.bldg.Devgiri, Chatrapati Shahu Sadan, Rajgad, Panchaganga No. 1 to 5. | 0.56 | 0.00 | 0.56 | completed | |
| 2010-2011 | MAR | S & C of R/C.bldg.Krishna Niwas, Om Sai Sadan, Ganesh Krupa (Elphinstone Road), Suyash, Nalanda, Shanti Niwas, Siddhi Sadan | 0.62 | 0.00 | 0.62 | completed | |
| 2010-2011 | MAR | S & C of R/C.bldg.Krishna Niwas, Om Sai Sadan, Ganesh Krupa | 0.26 | 0.00 | 0.26 | completed | |



| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| 2010-2011 | MAR | S & C of R/C.bldg.Pimpleshwar Krupa, Shivsmruti | 0.65 | 0.00 | 0.65 | completed | |
| 2010-2011 | MAR | S & C of R/C.bldg. Ambedkar Sadan, Vaishnav Sadan, M.Phule Sadan, Shivkripa, Shivratna, Vishranti. | 0.57 | 0.00 | 0.57 | completed | |
| 2010-2011 | MAR | S & C of R/C.bldg. Ambedkar Sadan, Vaishnav Sadan, M.Phule Sadan. | 0.53 | 0.00 | 0.53 | completed | |
| 2010-2011 | MAR | C.R.to R/C.bldg.Suyash. Rep.to I.P.S.flooring | 0.66 | 0.00 | 0.66 | completed | |
| 2010-2011 | MAR | C.R.to R/C.bldg.Siddhi Sadan. Rep.to damaged shahabad flooring | 0.63 | 0.00 | 0.63 | completed | |
| 2010-2011 | MAR | C.R.to R/C.bldg.Ambedkar Sadan. Replacement of damaged / rusted G.I.pipes. | 0.59 | 0.00 | 0.59 | completed | |
| 2010-2011 | MAR | Replacement of Rusted / Damaged G.I.pipes of R/C.bldg.Shivratna | 0.26 | 0.00 | 0.26 | completed | |
| 2010-2011 | MAR | Rep. to O.H.Water tank of R/C.Panchganga | 0.25 | 0.00 | 0.25 | completed | |
| 2010-2011 | MAR | Replacement of Rusted / Damaged G.I.pipes of R/C.bldg.Shahu Sadan | 0.13 | 0.00 | 0.13 | completed | |
| 2010-2011 | MAR | Replacement of Rusted / Damaged G.I.pipes of R/C.bldg.Shanti Niwas | 0.61 | 0.00 | 0.61 | completed | |
| 2010-2011 | . MAR | Replacement of Rusted / Damaged G.I.pipes of R/C.bldg.Shanti Niwas | 0.24 | 0.00 | 0.24 | completed | |
| 2010-2011 | MAR | Replacement of Rusted / Damaged G.I.pipes of R/C.bldg.Vaishnav Sadan, M.Phule Sadan | 0.63 | 0.00 | 0.63 | completed | |
| 2010-2011 | MAR | Replacement of Rusted / Damaged G.I.pipes of R/C.bldg.Nalanda, Suyash | 0.60 | 0.00 | 0.6 | completed | |
| 2010-2011 | MAR | Replacement of Rusted / Damaged G.I.pipes of R/C.bldg.Siddhi Sadan | 0.57 | 0.00 | 0.57 | completed | |
| 2010-2011 | MAR | Replacement of Rusted / Damaged G.I.pipes of R/C.bldg.Shivratna | 0.59 | 0.00 | 0.59 | completed | |



| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|--|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| 2010-2011 | MAR | Replacement of damaged decoyed common toilet and pump room door shutter of R/C.bldg.Ambedkar Sadan, Shivratna, M.Phule Sadan, Vaishnav Sadan | 0.28 | 0.00 | 0.28 | completed | |
| 2010-2011 | MAR | C.R.to R/C.bldg.Siddhi Sadan. | 0.64 | 0.00 | 0.64 | completed | |
| 2010-2011 | MAR | C.R.to R/C.bldg.Vishranti | 0.48 | 0.00 | 0.48 | completed | |
| 2010-2011 | MAR | Replacement of Rusted / Damaged G.I.pipes of R/C.bldg.M.Phule Sadan | 0.44 | 0.00 | 0.44 | completed | |
| 2010-2011 | MAR | C.R.to R/C.bldg.Nalanda | 0.17 | 0.00 | 0.17 | completed | |
| 2010-2011 | MAR | C.R.to R/C.bldg.Ambedkar Sadan | 0.56 | 0.00 | 0.56 | completed | |
| 2010-2011 | MAR | C.R.to R/C.bldg.Shahu Sadan, Pimpleshwar Kripa | 0.54 | 0.00 | 0.54 | completed | |
| 2010-2011 | MAR | Replacement of damaged / decoyed frame /shuter of pump room & head room of R/C. bldg.Tapovan A-B | 0.32 | 0.00 | 0.32 | completed | |
| 2010-2011 | MAR | C.R.to R/C. bldg. Tapovan B. Rep. to drainage line, R.S.ladi, pavement. | 0.63 | 0.00 | 0.63 | completed | |
| 2010-2011 | MAR | Rep. to loose / peeled off internal sofit plaster of tenament of R/C. bldg. Kokan Vaibhav. | 0.63 | 0.00 | 0.63 | completed | |
| 2010-2011 | MAR | Rep. to Gr. Floor / first floor common W.C.of R/C. bldg. Shivraj Bhavan 2. | 0.64 | 0.00 | 0.64 | completed | |
| 2010-2011 | MAR | Rep. to second Floor / third floor common W.C.of R/C. bldg. Shivraj Bhavan 2. | 0.61 | 0.00 | 0.61 | completed | |
| 2010-2011 | MAR | Rep. to forth Floor / fifth floor common W.C.of R/C. bldg. Shivraj Bhavan 2. | 0.65 | 0.00 | 0.65 | completed | |
| 2010-2011 | MAR | Replacement of decoyed frames / shuter of window of R/C. bldg, Jai Bhavani Sadan. | 0.65 | 0.00 | 0.65 | completed | |
| 2010-2011 | MAR | Replacement of damaged / leaking /outdated G.I.pipe / fitting of R/C. bldg. Siddhivinayak Kripa A wing | 0.53 | 0.00 | 0.53 | completed | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|--|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| 2010-2011 | MAR | Replacement of leaking / Corroded / outdated G.I.pipe / fitting on terrace of R/C. bldg. Tapovan A B. | 0.44 | 0.00 | 0.44 | completed | |
| 2010-2011 | MAR | S.R. to R/C. bldg. Siddhi Vinayak Kripa. Plastering & Painting | 0.43 | 0.00 | 0.43 | completed | |
| 2010-2011 | MAR | C.R.to R/C. bldg. Tapovan A. Rep. to drainage line, R.S.ladi, pavement. | 0.25 | 0.00 | 0.25 | completed | |
| 2010-2011 | MAR | Replacement of Corroded / leaking / downtake G.I.pipe / fitting, wheal stop tap of R/C. bldg.Kabirashram | 0.65 | 0.00 | 0.65 | completed | |
| 2010-2011 | MAR | Replacement of Corroded / leaking G.I.pipe / fitting on terrace of R/C. bldg.Siddhivinayak Kripa | 0.25 | 0.00 | 0.25 | completed | |
| 2010-2011 | MAR | Replacement of leaking / Corroded / outdated G.I.pipe / fitting feeding to R/C. bldg. Tapovan A B. | 7.67 | 0.00 | 7.67 | completed | |
| 2010-2011 | MAR | Replacement of damaged / leaking /outdated G.I.pipe / fitting of R/C. bldg. Siddhivinayak Kripa B wing | 0.61 | 0.00 | 0.61 | completed | |
| 2010-2011 | MAR | C.R.to R/C. bldg. Tapovan C. Rep. to C.C. pavement & Rough Shahabad. | 0.40 | 0.00 | 0.4 | completed | |
| 2010-2011 | MAR | Rep. to O.H.T of R/C bldg. Sai Shradha | 0.63 | 0.00 | 0.63 | completed | |
| 2010-2011 | MAR | Replacement of decoyed frame /shuter of Gr. Floor / first floor / second floor common W.C. of R/C. bldg.Laxmi Sadan | 0.63 | 0.00 | 0.63 | completed | |
| 2010-2011 | MAR | Replacement of decoyed frame /shuter of third floor / forth floor / fifth floor common W.C. of R/C. bldg.Laxmi Sadan | 0.64 | 0.00 | 0.64 | completed | |
| 2010-2011 | MAR | Replacement of decoyed frame /shuter of Common sanitory block of R/C. bldg. Jai Bhavan Sadan | 0.63 | 0.00 | 0.63 | completed | |



| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|--|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| 2010-2011 | MAR | Replacement of damaged / decoyed common door shuter of R/C. bldg. Jai Bhavan Sadan | 0.61 | 0.00 | 0.61 | completed | |
| 2010-2011 | MAR | Cleaning of U.G. & O.H. water tank of R/C. bldg.in khed gully & old prabhadevi under the jurisdiction of DE-1 | 0.51 | 0.00 | 0.51 | completed | |
| 2010-2011 | MAR | Cleaning of U.G. & O.H. water tank of R/C. bldg.under the jurisdiction of DE-1 | 0.42 | 0.00 | 0.42 | completed | |
| 2010-2011 | MAR | Replacement of deteriorated frame / shuter R.H.S. Sanitory block of R.C. bldg. Trishul 2 | 0.65 | 0.00 | 0.65 | completed | |
| 2010-2011 | MAR | Replacement of deteriorated frame / shuter L.H.S. Sanitory block of R.C. bldg. Trishul 2 | 0.65 | 0.00 | 0.65 | completed | |
| 2010-2011 | MAR | Cutting down trees & attending leakages in sanitory pipe fitting of R/C. under DE1 | 0.15 | 0.00 | 0.15 | completed | |
| 2010-2011 | MAR | S.R.to R/C. bldg. Mahalaxmi Darshan. Recastign of R.C.C.slab | 0.56 | 0.00 | 0.56 | completed | |
| 2010-2011 | MAR | S.R.to R/C. bldg. Sai Dham, datta ahire marg. | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Rep. to external plaster of pump house, U.G. S.T. & O.H.T. of R/C. bldg. Mahalaxmi Darshan | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Rep. to loose / peeled off internal sofit plaster to tenaments of R/C. bldg. Kokan Vaibhav. | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Rep. to rough shahabad stone flooring & Rep. to inspection chember, drainage line of R/C.bldg. Bajarang Kripa. | 2.28 | 0.00 | 2.28 | completed | |
| 2010-2011 | MAR | Replacement of damaged / corroded /downtake G.I.pipe / fitting of R/C. bldg. Sai Dham | 0.00 | 9.17 | 9.17 | completed | |
| 2010-2011 | MAR | Rep. to O.H.Water tank I of R/C.Bajrang Kripa | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Rep. to O.H.Water tank II of R/C.Bajrang Kripa | 0.65 | 0.00 | 0.65 | completed | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| 2010-2011 | MAR | Reconstruction of damaged portion & Rep. to peeled off plaster of compound wall of R/C.bldg. Kokan Vaibhav | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | S & C of R/C building Bramhasidhi, Ganeshprabha, Dattprasad, Sukhshanti, Dattkripa, Siddhisai. | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | S & C of R/C building Shivraj Bhavan 1&2, Satyam Shivam Sundaram, Kabirashram, Ganesh kripa(Std.Mill Lane), | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | S & C of R/C building Safalya 1& 2, Saidham | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | S & C of R/C building Bajrang Kripa, saisagar, Mahalaxmi Darshan, Tapovan A B C, Bhagirath, Ratnasidhu, Shamsunder Sadan. | 0.64 | 0.00 | 0.64 | completed | |
| 2010-2011 | MAR | S & C of R/C building Yugarambha, Ganesh Niketan, Adwait, Laxmi Sadan, Shree Ram Sadan, Sai Shradha, Vishwajyoti Sadan. | 0.44 | 0.00 | 0.44 | completed | |
| 2010-2011 | MAR | S & C of R/C building Swami Sadan, Sarang, Durga Niwas, Trishul 1&2, Kokan Vaibhav, Jai Bhavani Sadan. | 0.48 | 0.00 | 0.48 | completed | |
| 2010-2011 | MAR | C.R. work rep. to draingae arrangement of R/C.bldg.Jai Bhavani Sadan | 0.28 | 0.00 | 0.28 | completed | |
| 2010-2011 | MAR | C.R. work rep. to plinth protection of R/C.bldg.Jai Bhavani Sadan | 0.54 | 0.00 | 0.54 | completed | |
| 2010-2011 | MAR | S.R.to R/C.bldg. Safalya 1. Plastering & Painting | 0.32 | 0.00 | 0.32 | completed | |
| 2010-2011 | MAR | S.R.to R/C.bldg. Safalya 2. Plastering & Painting | 0.56 | 0.00 | 0.56 | completed | |
| 2010-2011 | MAR | S.R.to R/C.bldg. Laxmi Sadan. Plastering & Painting | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Rep. to pump houses, ele. Meter room of R/C.bldg, Tapovan A B | 0.00 | 0.00 | 0 | In Progress | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|--|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| 2010-2011 | MAR | C.R.to providing ceiling plaster to tenaments siporex slab of R/C. bldg. Laxmi Sadan | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Rep. to U.G.S.T.of R/C. bldg. Kabirashram | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Replacement of damaged P.V.C.soil / waste water / rain water / vent pipes of R/C. bldg. Shivraj Bhavan 1 & 2 | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Cutting down trees & attending leakages in sanitory pipe fitting of R/C. bldg. in khed gully & old prabhadevi under DE1 | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Compliance of R.C.O. Notices to being te OHT/ UGST of R/C. bldg. of G.S ward in mosquito proof conditions | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Sweaping & Cleaning of R/C. bldg.Pimpleshwar Kripa, Shivsmruti | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Tree cutting and leakage & repair of PVC pipes of R/C. bldg. as per list attached under DE-II | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | S.R.to Vinayak Sadan | 0.00 | 0.12 | 0.12 | completed | |
| 2010-2011 | MAR | Tree cutting and leakage & repair of PVC pipes of R/C. bldg. as per list attached under DE-II | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | S.R. to R/C. bldg. Shivsmruti | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | C.R.to R/C. bldg. Mahatma Phule Sadan & Vishranti, Rep. to interna plaster for rooms ceiling plaster. | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | C.R.to R/C. bldg. Mahatma Phule Sadan, attending leakages of O.H.Water Tank no.1 | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Sweaping & Cleaning of R/C. bldg.Ambedkar Sadan, Vaishnav Sadan, Mahatma Phule Sadan, Shivkripa, Shivratna, Vishranti. | 0.00 | 0.00 | 0 | In Progress | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|--|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| 2010-2011 | MAR | Sweaping & Cleaning of R/C. bldg.Devgiri,Shahu Sadan, Rajgad, Panchganga 1 to 5, Vinayak Sadan. | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Sweaping & Cleaning of R/C. bldg.Ambedkar Sadan, Mahatma Phule Sadan, Shivkripa, Shivratna, Vishranti. | 0.00 | 0.60 | 0.6 | completed | |
| 2010-2011 | MAR | Sweaping & Cleaning of R/C. bldg.Pimpleshwar Kripa, Shivsmruti | 0.00 | 0.56 | 0.56 | completed | |
| 2010-2011 | MAR | Repairs to loose/damaged ceiling of R/C. bldg. Devgiri | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Sweaping & Cleaning of R/C. bldg.Krishna Niwas, Om sai Sadan, Ganesh Kripa, Suyash, Nalanda , Shanti Niwas, Siddhi Sadan | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Repairs to loose/damaged ceiling of R/C. bldg. Panchganga I, 3, 4 & 5. | 0.52 | 0.00 | 0.52 | completed | |
| 2010-2011 | MAR | C.R. to R/C. bldg. shahu Sadan, Rep to Window Shutter & Frame | 0.29 | 0.00 | 0.29 | completed | |
| 2010-2011 | MAR | Replacement of damaged / decoyed common door shuter& frame of R/C. bldg. Shahu Sadan | 0.65 | 0.00 | 0.65 | completed | |
| 2010-2011 | MAR | Replacement of damaged / decoyed common door & Pump room doors, shuter of R/C. bldg. Shahu Sadan | 0.31 | 0.00 | 0.31 | completed | |
| 2010-2011 | MAR | Repairs to internal RCC members i.e.coloum bim, soffit of ground floor tenement of RC building Shri ram sadan | 0.65 | 0.00 | 0.65 | completed | |
| 2010-2011 | MAR | Rep. to internal RCC member i.e.slab, beams, columns of fourth floor tenements of RC bldg. Trishul no.2 | 0.00 | 0.00 | 0 | In Progress | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|--|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| 2010-2011 | MAR | Special repairs to Konkan Vaibhav, Plastring & Painting | 0.00 | 0.63 | 0.63 | completed | |
| 2010-2011 | MAR | Sweaping & Cleaning of RC bldg, Safalya 1 & 2, Saidham | 0.00 | 0.64 | 0.64 | completed | |
| 2010-2011 | MAR | Sweaping & Cleaning of RC bldg, Shivraj Bhavan 1 & 2, Satyam Shivam Sundaram, Kabirashram, Ganesh Kripa, Siddhivinayak Kripa | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Rep to Meter Room, Pump Room of RC bldg, Tapovan C & Rep. to damaged flooring of chowk portion of RC bldg. Tapovan A B | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Sweaping & Cleaning of RC bldg, Bramhasiddhi, Ganesh Prabha, Siddhi Prabha, Sanjivani Prasad, Sukhshanti, DattKripa, SiddhiSai | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Rep. to external faces & top portion of OHT & headroom of RC bldg, Saishraddha | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Providing waterproofing treatment to terrace roof slab of R/C. bldg. Devgiri | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | C.R. to R/C. bldg. M. Phule Sadan, Attending Leakages | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Sweaping & Cleaning of R/C. bldg.Krishna Niwas, Om sai Sadan, Ganesh Kripa, Suyash, Nalanda , Shanti Niwas, Siddhi Sadan | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | C.R. to R/C. bldg. M. Phule Sadan, Attending Leakages of O.H.Water Tank No.1 | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | | Sweaping & Cleaning of R/C. bldg.Swami Sadan, Durga Niwas, Trishul, Konkan Vaibhav, Jai Bhavani | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | | CR work providing weather shed & rep to north side staircase at RC bldg. Trishul No.2 | 0.00 | 0.00 | 0 | In Progress | |



| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| 2010-2011 | MAR | Sweaping & Cleaning of R/C. bldg.Bajrang Kripa, Saisagar, Mahalaxmi Darshan, Tapovan, Bhagirath, Ratnasindhu, Shamsunder Sadan. | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Sweaping & Cleaning of R/C. bldg.Yagarambha, Ganesh Niketan, Adwait, Laxmi Sadan, Shree Ram Sadan, Sai Shraddha, Vishvajyoti | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Rep. to internal RCC member i.e.slab, beams, columns of Ground floor tenements of RC bldg. Ganesh Kripa | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Rep to Ceiling of T/S. no. 110, 113, 406 pump house of RC. Bldg. Bramhasiddhi. | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Rep to OHT of RC. Bldg. Bhagirath | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Rep. to internal RCC member i.e.slab, beams, columns of RC bldg. Ganesh Prabha | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Replacement of corroded / outdated / leaking vertical G.I. pipe / fittings and wheeled stop tap of RC bldg. Konkan Vaibhav | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Rep to load carrying members of first floor tenements of RC bldg. Ganesh Kripa. | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Rep to badly deteriorated soffits of 3rd floor of RC bldg. Bramhasiddhi | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Rep to badly deteriorated soffits beams of 1st floor of RC bldg. Shree Ram Sadan | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Rep. to internal RCC member i.e.slab, beams, of T/S. no. 501, 503, 505 in RC bldg. Trishul No.1 | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Rep to 1st, 2nd, 3rd floor WC of RC bldg. Satyam Shivam Sundaram | 0.00 | 0.00 | 0 | In Progress | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| 2010-2011 | MAR | Rep to loose / peeled off internal cement plaster of RC bldg. Adwait | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Rep. to internal RCC member i.e.soffit, beams of common sanitory block, common varandha of RC bldg. Ganesh Prabha | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Rep to badly deteriorated columns, beams, soffits of 2nd floor of RC bldg. Ganesh Kripa | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Rep to loose / peeled off plaster of T/S. no. 501, 503, 504, 505 in RC bldg. Bramhasiddhi | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Rep to loose / peeled off plaster of soffits & beam of 2nd, 3rd floor RC bldg. Shree Ram Sadan | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Rep to loose / peeled off internal cement plaster of 2nd, 3rd floor RC bldg. Trishul No.2 | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Replacement of corroded / outdated G.I. pipe / fittings and wheeled stop tap of RC bldg. Konkan Vaibhav | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Rep to WC / Nahani of RC bldg. Siddhi Sai | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Rep to UGST pump house, rough shahabad stone flooring of RHS portion of RC bldg,. Ganesh Prabha | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Improvement in drainage system of Konkan Vaibhav | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Rep to loose / peeled off plaster of 3rd floor RC bldg. Ganesh Kripa | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Rep to loose Ceiling of tenement no.523, 524, 525 5th floor common varandah of RC. bldg. Bramhasiddhi | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Rep to soffit, beam of 4th floor, of RC bldg.Shree Ram Sadan | 0.00 | 0.00 | 0 | In Progress | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| 2010-2011 | MAR | Rep. to internal RCC member i.e. beams, Slab of T/S.no.507, 508, 510 of 5th floor, common varandah of RC bldg. Trishul No.1 | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Rep to ceiling beam of 4th floor, of RC bldg.Ganesh Kripa | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Rep / Replacement of leaking / damaged PVC pipes/ fitting & replacement of outdated corroded vertical fittings cutting trees of RC bldg.Ratnasindhu, Tapovan, Bhagirath, Shyam Sunder Sadan, Swami Sadan, Sarang | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Rep to WC / Nahani of RC bldg. Sukhshanti, Jay Bhavani Sadan | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Rep to 4th & 5th floor WC of RC bldg. Satyam Shivam Sundaram | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Rep to soffit, beam of 5th floor, of RC bldg.Ganesh Kripa | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Improvement in drainage system, Rep to rough shahabad stone flooring & CC pavement of RC bldg. Sai Shraddha | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Improvement in drainage system, & providing of rough shahabad stone flooring to rear side portion of RC bldg. Bhagirath | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Rep to Common varandah, staircase portion of RC bldg. Ganesh Kripa | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Rep to damaged / settled CC pavement / rough shahabad stone flooring of rear side portion of RC bldg. Shivraj Bhavan 1 | 0.00 | 0.00 | 0 | In Progress | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|--|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| 2010-2011 | MAR | Rep. to internal RCC member i.e. beams, Slab, column of T/S.of RC bldg. Ganesh Niketan | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Rep to loose / delapidated soffits RC bldg. Sukhshanti B | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Rep to damaged / settled CC pavement / rough shahabad stone flooring of rear side & around underground tank of RC bldg. Shivraj Bhavan 1 | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Rep to loose / peeled off plaster of soffits of 5th floor RC bldg. Siddhi Prabha | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Rep to damaged / settled CC pavement / rough shahabad stone flooring of right hand side portion of RC bldg. Shivraj Bhavan 2 | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Rep / Replacement of leaking / damaged PVC pipes/ fitting & replacement of outdated / corroded vertical G.I.pipe / fittings / cutting trees of RC bldg.Laxmi Sadan, Shree Ram Sadan, Vishvajyoti Sadan, Sai Shraddha, Kabirashram, Shivraj Bhavan 1 & 2, Satyam Shivam Sundaram | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Rep to damaged / settled CC pavement / rough shahabad stone flooring of left hand side portion of RC bldg. Shivraj Bhavan 1 | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Improvement in drainage system of RC bldg. Vishvajyoti Sadan | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Replacement deteriorated frame / shutter of window / door to RC bldg. Adwait, Saidham, Jai Bhavani | 0.00 | 0.00 | 0 | In Progress | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| 2010-2011 | . MAR | Rep / Replacement of leaking / damaged PVC pipes/ fitting & replacement of outdated / corroded vertical G.I.pipe / fittings / cutting trees of RC bldg.Siddhi Prabha, Ganesh Prabha, Dattprasad, Bramhsiddhi, Siddhivinayak Kripa, Ganesh Kripa | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | . MAR | Rep to soffit, beam of 4th floor, of RC bldg.Siddhi Prabha | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Improvement in drainage system of front side portion & left hand side house gully of RC bldg. Shivraj Bhavan 1 | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | . MAR | Rep / Replacement of leaking / damaged PVC pipes/ fitting & replacement of outdated / corroded vertical G.I.pipe / fittings / cutting trees of RC bldg.Datta Kripa, Sukhshanti, Sanjeevani Prasad, Siddhisai, Sai Sagar, Mahalaxmi Darshan, Safalya 1 & 2 | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Rep to Common varandah of RC bldg. Ganesh Niketan | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Improvement in drainage system of rear side portion of RC bldg. Shivraj Bhavan 1 | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | | Rep / Replacement of leaking / damaged PVC pipes/ fitting & replacement of outdated / corroded vertical G.I.pipe / fittings / cutting trees of RC bldg.Durga niwas, Trishul 1&2, jay Bhavani sadan, Bajrang Krupa, Adwait, Konkan Vaibhav, Saidham Ganesh Niketan &Yugarambh. | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Rep to rough shahabad stone, flooring, cc pavement of RC bldg. Vishvajyoti Sadan. | 0.00 | 0.00 | 0 | In Progress | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|--|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| 2010-2011 | MAR | Improvement in drainage system of rear side portion of RC bldg. Shivraj Bhavan 2 | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Replacement of leaking /Corrodated / Outdated G.I.Pipe, Fittings /feeding to R.C.bldg. Bajrang Kripa. | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Improvement in drainage system of Front side portion & Right Hand Side House Gully of RC bldg. Shivraj Bhavan 2 | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Replacement of detereodated frame/shutter of third floor/forth floor / fifth floor common sanitory block of R.C. bldg.Swami Sadan. | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Replacement of detereodated frame/shutter of first floor/ Second floor common sanitory block of R.C. bldg.Swami Sadan. | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | | C.R. to R.C.Bldg. Nalanda Niwas-Rep. to Chembers R.S. Ladi & Drainage Line. | 0.00 | 0.65 | 0.65 | completed | |
| 2010-2011 | MAR | C.R. to R.C.Bldg. Shanti Niwas-Attending leakages of OHT. | 0.00 | 0.64 | 0.64 | completed | |
| 2010-2011 | MAR | S.R.to R.C.bldg.Shivratna. | 0.00 | 7.86 | 7.86 | completed | |
| 2010-2011 | MAR | S.R.to R.C.bldg.Nalanda Niwas.Plastering & Painting | 0.00 | 8.39 | 8.39 | completed | |
| 2010-2011 | MAR | C.R. to R.C.Bldg. Chatrapati Shahu Sadan, Panchganaga, Pimpleshawar Kripa.Rep. to PVC pipe. | 0.00 | 0.62 | 0.62 | completed | |
| 2010-2011 | MAR | C.R. to R.C.Bldg. Ambedkar Sadan. Providing & fixing of CI cover with chember. | 0.00 | 0.60 | 0.6 | completed | |
| 2010-2011 | MAR | Replacement of damaged / ruster GI pipe. Stop tap to R.C.bldg.Vaishnav Sadan. | 0.00 | 0.58 | 0.58 | completed | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| 2010-2011 | MAR | C.R. to R.C.Bldg. Shivratna & M.Phule Sadan.Attending leakages of W.C.Bath. | 0.00 | 0.62 | 0.62 | completed | |
| 2010-2011 | MAR | Replacement of damaged / ruster GI pipe. Stop tap to Pump line of R.C.bldg.M.Phule Sadan. | 0.00 | 0.63 | 0.63 | completed | |
| 2010-2011 | MAR | Rep to deteriodated beam slab of Gr.floor/1st / 2nd floor of RC bldg.Shivam of Satyam Shivam Sundaram | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | S & C of R.C. bldg. Safalya 1 & 2, Saidham. | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | S & C of R.C. bldg. Bramhasiddhi, Ganeshprabha, Dattprasad, Siddhiprabha, Sanjeevaniprasad, Sukhshanti, Dattkripa, siddhisai. | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | S & C of R.C. bldg. Yugarambha, Ganesh Niketan, Adwait, Laxmi Sadan, Shree Ram Sadan, Sai Shraddha, Vishwajyoti Sadan. | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | S & C of R.C. bldg. Bajrang Kripa, Sai sagar, Mahalaxmi Darshan, Tapvan , Bhagirath, Ratnasindhu, Shyam sunder sadan. | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | | S & C of R.C. bldg. Swami Sadan, Sarang, Durga Niwas, Trishul 1 & 2, Konkan Vaibhav, Jai Bhavani. | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | S & C of R.C. bldg. Shivraj Bhavan 1 & 2, Satyam Shivam Sundaram, Kabirashram, Ganesh Kripa, Siddhivinayak Kripa. | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | | Rep to Siporex Slab to R.C.bldg. Siddhi Sai. | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | | C.R. to R.C.Bldg. Chatrapati Shahu Sadan, Rep. to Windows & shutter. | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Replacement of corrodated / outdated leakages of GI pipe , fitting of R.C.bldg.Sukhshanti-A | 0.00 | 0.66 | 0.66 | completed | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| 2010-2011 | . MAR | Replacement of corrodated / outdated leakages of GI pipe , fitting of R.C.bldg.Sukhshanti-A | 0.00 | 0.67 | 0.67 | completed | |
| 2010-2011 | . MAR | S & C of R.C. bldg. Krishna Niwas, Om Sai Sadan, Ganesh Kripa, Suyash, Nalanda, Shanti Niwas, Siddhi Sadan. | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | S & C of R.C. bldg. Pimpleshwar Kripa, Shivsmruti, | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | . MAR | S & C of R.C. bldg. Ambedkar Sadan, Vaishnav Sadan, M.Phule Sadan, Shivkripa, Shivratna, Vishranti Sadan, | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | S & C of R.C. bldg. Devgiri, Shahu Sadan, Rajgad, Panchganga 1 to 5, Vinayak Sadan. | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | . MAR | Streatning to RCC member of 2nd /1st / gr floor tenants of RC bldg. Satyam of Satyam Shivam Sundaram | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | | Rep to loose / peeled off plaster of 5th /4th /3rd floor tenements of RC bldg. Satyam of Satyam Shivam Sundaram | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | | Internal Rep to OHT of RC bldg. Adwait | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | . MAR | Rep to Settled CC & rough shahbad flooring of left hand side & rear side portion of RC bldg. Satyam of Satyam Shivam Sundaram | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | . MAR | Rep to internal RCC members I.E.beam soffits of 3rd /4th /5th floor tenements of RC bldg. Shivam of Satyam Shivam Sundaram | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | . MAR | Replacement of corroded / leaking / outdated loopline on terrace , pumping lline, feeding main etc. G.I.pipe/fittings of RC bldg. Ganesh Prabha | 0.00 | 0.00 | 0 | In Progress | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| 2010-2011 | MAR | Rep to Soffit, beam of Gr./1st /2nd floor tenements of RC bldg. Sundaram of Satyam Shivam Sundaram | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | | Rep to loose / peeled off plaster of third floor /forth /fifth floor tenements of RC bldg. Sundaram of Satyam Shivam Sundaram | 0.00 | 0.00 | 0 | In Progress | |
| 2010-2011 | MAR | Raje Shivaji | 6.28 | 0 | 6.28 | Completed | |
| 2010-2011 | MAR | Samadhan | 0.58 | 0 | 0.58 | Completed | |
| 2010-2011 | | Datta Niwas | 5.71 | 0 | 5.71 | Completed | |
| 2010-2011 | MAR | Progressive A, B, C-1 & C-2 | 13.43 | 0 | 13.43 | Completed | |
| 2010-2011 | MAR | Shubhangan | 11.91 | 0 | 11.91 | Completed | |
| 2010-2011 | MAR | Omkar A-1 | 6.65 | 0 | 6.65 | Completed | |
| 2010-2011 | MAR | Omkar B-2 | 6.8 | 0 | 6.8 | Completed | |
| 2010-2011 | MAR | Vithal Krupa | 8.22 | 0 | 8.22 | Completed | |
| 2010-2011 | MAR | Kranti Niwas, Panchsheel & Ashakunj | 8.41 | 0 | 8.41 | Completed | |
| 2010-2011 | MAR | Taqdeer Niwas | 5.7 | 0 | 5.7 | Completed | |
| 2010-2011 | MAR | Progressive C-2 | 8.36 | 0 | 8.36 | Completed | |
| 2010-2011 | MAR | Progressive C-1 | 7.81 | 0 | 7.81 | Completed | |
| 2010-2011 | MAR | Panchsheel | 14.8 | 0 | 14.8 | In Progress | |
| 2010-2011 | | Repairs to Shivshakti Bldg. rooms & passage ceiling with siporex powder in E ward, Mumbai. | 0.58 | 0 | 0.58 | Completed | |
| 2010-2011 | | CR to reconst. Bldg. Abhinandan in E ward, repairs to PVC pipes. | 0.58 | 0 | 0.58 | Completed | |
| 2010-2011 | | CR to reconst. Bldg. Abhinandan in E ward, repairs to U.G. Tank No.1 | 0.62 | 0 | 0.62 | Completed | |
| 2010-2011 | | CR to reconst. Bldg. Abhinandan in E ward, repairs to U.G. Tank No.2 & pump room. | 0.58 | 0 | 0.58 | Completed | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|--|-----------------------------------|------------------------------------|----------------------|------------------------|---------|
| | | CR to cleaning & washing of U.G.Tank & O.H. water tank | | | | Completed | |
| 2010-2011 | MAR | from inside of RC bldg. in E ward, | 0.5 | 0 | 0.5 | 0 14 1 | |
| | | Densing a stale many algorithm and a superson tailet do an abuttan | | | | Completed | |
| 2010 2011 | | Repairing of damage/decayed common toilet door shutter | 0.45 | 0 | 0.45 | | |
| 2010-2011 | MAR | & frame of RC Bldg.known as Ashirwad in ward, Mumbai. | 0.45 | 0 | 0.45 | | |
| | | Replacement of drainage decayed common toilet door | | | | | |
| 2010-2011 | MAR | shutter and frame of R/C bldg.Ashirwad in E ward. | 0.59 | 0 | 0.59 | Completed | |
| 2010 2011 | | C.R. to R/C Bldg. Pragati in E ward, repairs to tenaments | 0.37 | 0 | 0.35 | Completed | |
| 2010-2011 | MAR | room and passage ceiling plaster | 0 | 0 | 0 | - | |
| 2010-2011 | MAR | Sweeping & Cleaning work of bldg. known as Konkan Manzil, Durga Bhavan , Panchsheel , Raja Dashrath, Kranti Niwas, Taqdeer Niwas, Gaodevi Darshan, Shubhangan, Sankalp Niketan , Datta Niwas & Audumbar in E 1 ward. | 0.44 | 0 | 0.44 | Completed | |
| 2010-2011 | | Sweeping & Cleaning work of bldg. Abhinanadan, Pragati, Raje Shivaji, Omkar, Saikrupa, Vitthalkrupa, Ambika Niwas, Dwarkamai, & Ashakunj in E - 1 ward. Sweeping & Cleaning work of Bldg.known as Jagat | 0.59 | 0 | 0.59 | Completed Completed | |
| | | Smruti, Gurusadan , Mandar Niketan and Gharkul in E - 1 | | | | | |
| 2010-2011 | MAR | ward. | 0.31 | 0 | 0.31 | 0 1 1 | |
| 2010-2011 | MAR | Sweeping & Cleaning work of bldg. known as Samadhan , Sahajeevan, Ashirwad 1 & 2 , Indraprasth, Sahakar Sadan 1 & 2 in E ward. | 0.6 | 0 | 0.6 | Completed | |
| 2010-2011 | MAR | Sweeping & Cleaning work of bldg. Shivshakti, Shivdarshan, Ashtavinayk, Progressive A, B, C1 & C2 in E -1 ward. | 0.5 | 0 | 0.5 | Completed | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|--|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| | | Demolition of bldg. No. 58 & 58A, Parmar Bldg., | | | | Completed | |
| 2010-2011 | MAR | Matharpakhadi Road, in E - 1 ward. | 0.55 | 0 | 0.55 | | |
| | | Replacement of damage dacayed window & frame of R/C | | | | Completed | |
| 2010-2011 | MAR | bldg. Ashirwad No.2 in E ward. | 0.6 | 0 | 0.6 | | |
| | | Replacement of damage decayed window & frame of R/C | | | | Completed | |
| 2010-2011 | MAR | bldg. Ashirwad No.2 in E ward. | 0.6 | 0 | 0.6 | | |
| | | | | | | Completed | |
| | | Repairs to G.I. Pipe of R/C bldg. known as Shivshakti in E | | | | | |
| 2010-2011 | MAR | - 1 ward, throguh C.R. Fund for the year 2009-10. | 0.23 | 0 | 0.23 | | |
| | | C.R. to R/C Bldg. Kranti Niwas in E - 1 ward, Attending | | | | Completed | |
| 2010-2011 | MAR | leakages to room nahani and w.c. | 0 | 0 | 0 | | |
| | | C.R. to RC Bldg. Indraprastha in E-1 ward repairs OH | | | | Completed | |
| 2010-2011 | MAR | tank (Flusing) Tank No.1 | 0 | 0 | 0 | | |
| | | C. R. RC Bldg. Indraprastha in E-1 ward repairs to OH | | | | | |
| 2010-2011 | MAR | tank (Flusing) Tank No.2 | 0 | 0 | 0 | In Progress | |
| | | Repairs to G.I. Pipe and gate valve of R/C Bldg. known as | | | | | |
| 2010-2011 | MAR | Kokan Manzil in E-1ard through CR Fund. | 0.24 | 0 | 0.24 | Completed | |
| | | Repairs to GI Pipe and gate valve of R/C bldg. known as | | | | ^ | |
| | | Ashirwad in E-1 ward through CR fund for the year 2009- | | | | | |
| 2010-2011 | MAR | 10 | 0.6 | 0 | 0.6 | Completed | |
| | | Repairs to GI pipe and gate valve of R/C bldg. known as | | | | Completed | |
| | | Mandar Niketan in E-1ward through CR Fund for the year | | | | | |
| 2010-2011 | MAR | 2009-10 | 0.6 | 0 | 0.6 | | |
| | | | | | | Completed | |
| | | Repairs to PVC pipe and cutting down small trees of R/C | | | | | |
| 2010-2011 | MAR | bldg known as Indraprastha in E-1 ward Mumbai. | 0.6 | 0 | 0.6 | | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|--|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| 2010-2011 | MAR | Repairs to PVC pipe and cutting down small trees of R/C bldg known as Panchsheel, Kokan Manzil, Durga Bhavan, Sankalp in E-1 ward Mumbai through CR Fund for the year 2009-10 | 0.62 | 0 | 0.62 | Completed | |
| 2010-2011 | MAR | Repairs to GI pipe of RC Bldg. known as Vitthal Krupa, Omkar A1, A2, B1, B2 in E-1 ward Mumbai. | 0.59 | 0 | 0.59 | Completed | |
| 2010-2011 | MAR | Attending leakages from room Nahanies of RC bldg. Shiv Shakti ,Telli Gulli, in E ward, Mumbai , through C.R. Fund 2009-10 | 0.59 | 0 | 0.59 | Completed | |
| 2010-2011 | MAR | Repairs to GI pipe and gate valve of RC building known as Raja Dashrath in E-1 ward through CR Fund for the year 2009-10 | 0.57 | 0 | 0.57 | Completed | |
| 2010-2011 | MAR | Repairs to GI pipe and gate valve of RC building known as Astavinayak , Telly gulli, Sivdarshan in E-1 ward through CR Fund for the year 2009-10 | 0.55 | 0 | 0.55 | Completed | |
| 2010-2011 | MAR | Repair to PVC pipe and cutting down small trees of R/C building known as Raja Dashrath, Gaodevi, Shubhangan, Takdeer Niwas and Kranti Niwas in E-1 ward, Mumbai. | 0.6 | 0 | 0.6 | Completed | |
| 2010-2011 | MAR | Repairs to PVC pipe and cutting down small trees of R/C bldg. known as Abhinandan, Omkar A1-A2,B1-B2 in E-1 ward, through CR Fund. | 0.6 | 0 | 0.6 | Completed | |
| 2010-2011 | MAR | Repair to PVC pipe and cutting down trees of R/C building known as Ashtvinayk, Shivshakti, Shivdarshan in E-1 ward, Mumbai. | 0.62 | 0 | 0.62 | Completed | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS |
|-----------|-------|--|-----------------------------------|------------------------------------|----------------------|----------------|
| | | C.R.repair to PVC pipe and cutting down trees of R.R.Bldg known as Raja Shivaji , Pragati.,Audumbar, Mandar | | | | Completed |
| 2010-2011 | MAR | Niketan in E-1 ward through CR Fund in Mumbai. | 0.63 | 0 | 0.63 | |
| 2010-2011 | MAR | CR to RC Bldg. Sahajeevan at Bakra-adda in E-1 ward Improvement in Drainage line and plinth protection. | 0.62 | 0 | 0.62 | Completed |
| 2010-2011 | | Repairs to PVC pipe and cutting down trees of R/C building knwona as Sahakar No.1, Sahakar NO.2, Progressive A, B, C1,C2 in E-1 ward through CR Fund for the year 2009-10 | 0.62 | 0 | 0.62 | Completed |
| 2010-2011 | MAR | Repairs to GI pipe and gatevalve of RC building known as Ashirwad-2 in E-1 ward throguh CR Fund for the year 2009-10 | 0.6 | 0 | 0.6 | Completed |
| 2010-2011 | | C.R. Repair to GI pipe and valve of R/C bldg. known as Abhinandan in E-1 ward, Mumbai. | 0.58 | 0 | 0.58 | Completed |
| 2010-2011 | MAR | Repair to PVC pipe and cutting down small trees of R/C bldg. known as Saikrupa, Vithalkrupa, Dwarkamai, Ambika niwas, Ashakunj in E-1 ward through CR Fund. | 0.62 | 0 | 0.62 | Completed |
| 2010-2011 | | C.R. to R/C bldg. Sahjeevan at Bakra-adda in E-1 ward providing Rough Shahabad Laddi | 0.62 | 0 | 0.62 | Completed |
| 2010-2011 | | Repairs to GI pipe and gate valve of R/C building known as Sankalp Niketan, Durga Bhavan in E-1 ward throguh C.R. Fund 2009-10. | 0.57 | 0 | 0.57 | Completed |



| S | REMARKS |
|---|---------|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |



| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS |
|-----------|-------|--|-----------------------------------|------------------------------------|----------------------|----------------|
| | | | | | | Completed |
| | | Repairs to GI pipe and gate valve of R/C bldg known as | | | | |
| 2010-2011 | MAR | Gaodevi, Krantisada, Shubhangan, Taqdeer Niwas in E-1 ward through C.R. Fund for the year 2009-2010 | 0.23 | 0 | 0.23 | |
| 2010 2011 | | | 0.20 | | 0.23 | Completed |
| | | Repairs to GI pipe and gate valve of R/C bldg. known as | | | | |
| | | Progressive A, B, C-1, C-2, Sahakar No.2 in E-1 ward | | | | |
| 2010-2011 | l MAR | through CR Fund for the year 2009-2010 | 0.25 | 0 | 0.25 | Completed |
| | | Repairs to GI pipe and gate valve of R/C building known | | | | Compiona |
| | | as Dwarkamai, Saikrupa, Ambika Niwas, Ashakunj in E-1 | | | | |
| 2010-2011 | MAR | ward through CR Fund for the year 2009-10 | 0.23 | 0 | 0.23 | |
| | | Repairs to GI pipe and gate valve of R/C building known | | | | Completed |
| 2010-2011 | | as Samadhan, Indraprastha, Sahajeevan in E-1 ward through CR Fund for the year 2009-10. | 0.23 | 0 | 0.23 | |
| 2010-2011 | | Providing Anti termite treatment to R/C bldg. known as | 0.23 | 0 | 0.23 | Completed |
| | | Progressive A, B, in E-1 ward through CR Fund 2009- | | | | |
| 2010-2011 | MAR | 2010 | 0.5 | 0 | 0.5 | |
| | | Providing Anti termite treatment to R/C bldg. known as | | | | Completed |
| 2010-2011 | MAR | Progressive C1, C2 in E-1 ward through CR Fund 2009- 2010 | 0.49 | 0 | 0.49 | |
| 2010 2011 | | 2010 | 0.17 | 0 | 0.45 | Completed |
| | | Providing Anti termite treatment to R/C bldg. known as | | | | |
| 2010-2011 | MAR | 'Shivdarshan' in E-1 ward through CR fund 2009-2010. | 0.45 | 0 | 0.45 | |
| | | Repair to GI pipe and gate valve of R/C bldg. knonw as | | | | Completed |
| 2010-2011 | MAR | Gharkul in E-1 ward through CR fund for the year 2009- 2010 | 0.62 | 0 | 0.62 | |
| 2010-2011 | | 2010 | 0.02 | 0 | 0.02 | |



| S | REMARKS |
|---|---------|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |



| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| | | Repair to GI pipe and gate valve of RC building known as | | | | Completed | |
| 2010-2011 | MAR | Raja shivaji , Panchsheel in E-1 ward through CR Fund for the year 2009-2010. | 0.55 | 0 | 0.55 | | |
| | | Repairs to PVC pipe and tree cutting to R/C bldg. known | | | | Completed | |
| | | as Jagasmruti in E-1 ward through CR fund for the year | | | | | |
| 2010-2011 | MAR | 2009-2010 | 0.62 | 0 | 0.62 | | |
| | | Providing Antitermite treatment to RC bldg. known as | | | | Completed | |
| | | Astavinayak-A and B wing in E ward through CR Fund for | | | | | |
| 2010-2011 | MAR | the year 2009-2010. | 0.62 | 0 | 0.62 | | |
| | | Sweeping and cleaning work of Jagatsmruti, Gurusadan, | | | | Completed | |
| | | Mandar Niketan, Gharkul in E-1 ward for period 01.03.10 | 0.01 | | | | |
| 2010-2011 | MAR | to 31.05.10 | 0.31 | 0 | 0.31 | Completed | |
| | | Sweeping & Cleaning work of Abhinandan, Pragati, Raje | | | | Completed | |
| | | Shivaji, Omkar, Saikrupa, Ambika Niwas, Dwarkamai, | | | | | |
| 2010-2011 | MAR | Ashakunj in E-1 ward period 01.03.10 to 31.05.2010 | 0.59 | 0 | 0.59 | | |
| 2010 2011 | | Repairs to GI pipe and gatevalve to R/C bldg. known as | | | 0.00 | Completed | |
| | | Shivshakti, Sahakar No.1 in E-1 ward, through CR fund | | | | | |
| 2010-2011 | MAR | 2009-10 | 0.58 | 0 | 0.58 | | |
| | | CR to RC bldg. Abhinandan in E-1 ward . Repairs to GI | | | | | |
| 2010-2011 | MAR | pipe (Pipe line) & Chamber. | 0.61 | 0 | 0.61 | Completed | |
| | | Sweeping & cleaning work of R/C bldg. Shivshakti, | | | | Completed | |
| | | Shivdarshan, Astavinayak , Progressive A,B,C1 & C2 in E- | | | | | |
| 2010-2011 | MAR | 1 ward. Period 01.03.2010 to 31.05.2010 | 0.5 | 0 | 0.5 | | |
| | | CR to RC bldg. known as Omkar A-2 in E-1 ward. Repairs | | | | Completed | |
| | | to damaged S.W. Line & Chamber & Rough Shahabad | | | | | |
| 2010-2011 | MAR | Flooring. | 0.56 | 0 | 0.56 | | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| | | CR to R/C Bldg. known as Omkar A-1, B-1 in E-1 ward. | | | | | |
| 2010-2011 | MAR | Repair to damaged S.W. Line Chamber & Rough Shahabad flooring. | 0.57 | 0 | 0.57 | Completed | |
| 2010 2011 | | CR to R/C bldg. known as Omkar B-2 in E-1 ward . | 0.07 | Ŭ | 0.07 | Completed | |
| | | Repairs to damaged S.W. line & chamber and rough | | | | | |
| 2010-2011 | MAR | Shahabad flooring. | 0.62 | 0 | 0.62 | | |
| | | Providing Antitermite treatment to RC bldg. Shivshakti A | | | | Completed | |
| 2010-2011 | MAR | wing in E-1 ward. | 0.6 | 0 | 0.6 | | |
| | | Sweeping & Cleaning Kokan Manzil, Durga Bhavan, | | | | Completed | |
| | | Panchsheel, Rajadarshrath, Kranti Niwas, Taqdeer Niwas, | | | | | |
| | | Gaodevi Darshan, Shivsayadri, Sankalp Niketan, Datta | | | | | |
| 2010 2011 | | Niwas, Audumbar in E - 1 ward Time period 01.03.2010 to | 0.44 | 0 | | | |
| 2010-2011 | MAR | 31.05.2010 | 0.44 | 0 | 0.44 | | |
| 2010 2011 | MAD | Sweeping & cleaning work of Samadhan , Sahajeevan, Ashirwad No.1 & 2 in E - 1 ward | 0 | 0 | 0 | In Drograss | |
| 2010-2011 | IVIAK | Sweeping & Cleaning work of Indraprasth, Sahakar Sadan | | 0 | 0 | In Progress | |
| 2010-2011 | MAR | No.1 & 2 in $E - 1$ ward. | 0 | 0 | 0 | In Progress | |
| 2010 2011 | | CR to R/C Bldg. Omkar A-2 in E-1 ward Repair to O. H. | 0 | Ŭ | | 1111051000 | |
| 2010-2011 | MAR | Water tank | 0.6 | 0 | 0.6 | Completed | |
| | | C. R. to R/C Bldg. known as Vitthal Krupa at Mazgaon in | | | | * | |
| 2010-2011 | MAR | E - 1 ward repair to O.H.W.Tank | 0.24 | 0 | 0.24 | Completed | |
| | | C.R.to R/C Bldg. known as Taqdeer Niwas, Shubhangan, | | | | Completed | |
| | | Kranti Sadan & Sankalp Niketan in E- 1ward. Repair to | | | | | |
| 2010-2011 | MAR | water meter chamber | 0.23 | 0 | 0.23 | | |
| | | C.R. to Gharkul in E - 1 ward, Improvement in Drawing in | | | | Completed | |
| 2010-2011 | MAR | E - 1 ward | 0.62 | 0 | 0.62 | | |
| | | Repair to G.I. pipe & Gate valve of RC buildg. Known as | | | | Completed | |
| 2010-2011 | MAR | Ghokul in E-1 ward through CR fund | 0.23 | 0 | 0.23 | | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|--|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| | | Sweeping and Cleaning work of Bldg. known as Konkan Manzil, Durga Bhavan, Panchseel , Raja Dashrath, Kranti Niwas, Taqdeer Niwas, Gaondevi Darshan, Shubhangan, Sankalp Niketan, Datta-Niwas, Adumbar & Sahakar | | | | Completed | |
| 2010-2011 | MAR | Sadan No.1 & 2 in E ward. | 0.58 | 0 | 0.58 | | |
| 2010-2011 | MAR | Sweeping & Cleaning work of Bldg. known as Abhinandan, Pragati, Raja Shivaji, Omkar, Saikrupa, Vitthal krupa, Ambika Niwas, Dwarkamai, Ahsakunj in E-1 ward. | 0 | 0 | 0 | Completed | |
| 2010-2011 | MAR | Sweeping & Cleaning of R/C bldg. known as Shivshakti , Shivdarshan, Astavinayak , Progressive A, B & C1 & C2 & Indraprastha in E-1 Divn. | 0 | 0 | 0 | Completed | |
| 2010-2011 | MAR | C. R. to Cleaning & Washing of U.G. Tank & O.H. Water Tank from inside of R/C Bldg. in E-1 ward. | 0 | 0 | 0 | Completed | |
| 2010-2011 | MAR | Repair to G.I. pipe & Gate valve of R/C Bldg. known as Pragati in E-1 Div, through C.R.Fund. | 0 | 0 | 0 | Completed | |
| | | Repair to PVC Pipe & Cutting down small tree of R/C bldg. known as Durga Bhavan, Kokan Manzil, Audumbar, & | | | | Completed | |
| 2010-2011 | MAR | Pragati in E-1 Div through CR Fund. | 0.62 | 0 | 0.62 | | |
| 2010-2011 | MAR | Repair to G.I. Pipe & Gate Valve of R/C Bldg. known as vithal Krupa in E-1 Divn through CR Fund | 0.23 | 0 | 0.23 | Completed | |
| | | Repair to PVC pipe & cutting down small trees of R/C bldg. known as Sahakar Sadan No.1 , Sahakar Sadan No.2, Sankalp Niketan, Raje Shivaji in E - 1 Div., through | | | | Completed | |
| 2010-2011 | MAR | CR Fund. | 0.56 | 0 | 0.56 | Completed | |
| 2010-2011 | MAR | Repair to G.I. Pipe of R/C Bldg. known as Kranti Niwas in E-1 Div through CR Fund. | 0.18 | 0 | 0.18 | Completed | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| | | Repair to OH and UG Tank C.I. Manhole cover of R/C | | | | Completed | |
| | | Bldg. known as Datta Niwas , Rajashivaji, Shivshakti & | | | | | |
| 2010-2011 | L MAR | Progressive B in E-1 CR Fund. | 0.31 | 0 | 0.31 | | |
| | | Repair to PVC pipe & cutting down small tree of R/C | | | | Completed | |
| | | bldg.known as Omkar A1, A2,B1, B2 , Shivshakti in E-1 | | | | | |
| 2010-2011 | L MAR | Divn through CR Fund. | 0.62 | 0 | 0.62 | | |
| | | Repair to PVC pipe & cutting down small tree to R/C bldg. | | | | Completed | |
| | | known as Indraprasth, Progressive A,B,C1 & C2 in E-1 | | | | | |
| 2010-2011 | MAR | Divn through CR Fund. | 0.45 | 0 | 0.45 | | |
| | | Repair to PVC pipe & cutting down small trees to R/C | | | | Completed | |
| | | Bldg. known as Abhinandan, Astavinayak , Shivdarshan, | | | | | |
| 2010-2011 | MAR | E-1 Divn, through CR Fund | 0.49 | 0 | 0.49 | | |
| | | Repair to GI pipe and Gate valve of R/C bldg. known as | | | | Completed | |
| 2010-2011 | L MAR | Astavinayak , Shivdarshan in E-1 Divn. | 0.47 | 0 | 0.47 | | |
| | | Repair to G.I. pipe and Gate valve of R/C Bldg. known as | | | | Completed | |
| 2010-2011 | MAR | Progressive A,B, C1 & C2 in E-1 Divn. | 0.55 | 0 | 0.55 | | |
| | | Repair to 6" pipe & Gate valve of R/C Bldg.known as | | | | Completed | |
| 2010-2011 | L MAR | Astavinayak, Shivdarshan in E-1 Divn. | 0.39 | 0 | 0.39 | | |
| | | Repair to G.I. Pipe and Gate valve of R/C Bldg. known as | | | | Completed | |
| | | Ambika niwas, Sai krupa, Ashakunj, Dwarkamai in E-1 | | | | | |
| 2010-2011 | MAR | Divn. | 0.55 | 0 | 0.55 | | |
| | | Repair to G.I pipe and Gate valve of R/C Bldg. known as | | | | Completed | |
| 2010-2011 | MAR | Omkar A1, A2, B1 & B2 in E-1 Divn | 0.52 | 0 | 0.52 | | |
| | | Repair to G.I. Pipe & Gate Valve of R/C bldg. known as | | | | Completed | |
| 2010-2011 | MAR | Audumber, Indraprasth in E-1 Divn. | 0.23 | 0 | 0.23 | | |
| | | Sweeping & Cleaning work of R/C Bldg. Known as | | | | Completed | |
| | | Shivshakti, Shivdarshan, Ashtavinayak, Progressive A,B, | | | | | |
| 2010-2011 | L MAR | C1 & C2 & Indraprastha in E-1 Divn. | 0.62 | 0 | 0.62 | | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|--|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| | | Repair to G.I. Pipe and Gate value of R/C bldg. known as | | | | Completed | |
| 2010-2011 | MAR | Sahakar No.1, Sahakar No.2 in E-1 Divn. | 0.38 | 0 | 0.38 | | |
| 2010-2011 | MAR | Sweeping & Cleaning of Bldg. known as Pragati, Abhinandan, Raja Shivaji, Omkar , Saikrupa, Vitthal krupa, Ambika niwas, Ashakunj, Dwarkamai in E-1 Divn. | 0.59 | 0 | 0.59 | Completed | |
| | | Repair to G.I. Pipe & Gate valve of R/C bldg. known as Gaondevi Darshan, Raja Dashrath, Kokan Manzil, in E-1 | | | | Completed | |
| 2010-2011 | MAR | Divn. | 0.4 | 0 | 0.4 | | |
| 2010-2011 | MAR | Repair to G.I. Pipe & Gate valve of R/C bldg. known as Sankalp Nikten, Dattaniwas & Durgabhavan, in E-1 Divn. | 0.42 | 0 | 0.42 | Completed | |
| 2010 2011 | MAD | Sweeping & Cleaning work of bldg. known as Kokan Manzil, Durga Bhavan, Panchsheel, Raja Dashrath, Kranti Niwas, Taqdeer Niwas, Shubhangan, Sankalp Niketan, Dattaniwas, Audumbar, Sahakar Sadan No.1 & 2 in E-1 Div. | | 0 | 0.58 | Completed | |
| 2010-2011 | IVIAR | Repair to Nahani & W.C. of R/C Bldg. Known as | 0.58 | 0 | 0.58 | Completed | |
| 2010-2011 | MAR | Progressive C1 at Chinchpokli in E-1 Divn. | 0.55 | 0 | 0.55 | <u>^</u> | |
| 2010 2011 | | Repair to PVC pipe & cutting down trees of R/C bldg.known as Progressive C1 & C2 , Omkar A1 & A2 in | | | 0.55 | Completed | |
| 2010-2011 | MAR | E-1 divn. | 0.42 | 0 | 0.42 | | |
| 2010-2011 | MAR | Repair to Nahani & W.C. of R/C Bldg. Known as Indraprasth at Chinchpokli in E-1 Divn. | 0.61 | 0 | 0.61 | Completed | |
| | | Repair to Chamber & G.I. Pipe in BMC line of R/C Bldg. known as Sankalp Niketan, Durga Bhavan, Kokan Manzil, Omkar A1 & A2 , Shivshakati & Sahakar Sadan No.2 in E- | | 0 | | Completed | |
| 2010-2011 | MAR | 1 Divn. | 0.59 | 0 | 0.59 | | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| | | Repair to Nahani & W.C. of R/C Bldg. Known as | | | | Completed | |
| 2010-2011 | MAR | Progressive C2 at Chinchpokli in E-1 Divn. | 0.59 | 0 | 0.59 | | |
| | | Repair to G.I. Pipe and Gate valve in BMC of R/C Bldg. | | | | Completed | |
| 2010-2011 | MAR | known as Abhinandan in E-1 Divn | 0.57 | 0 | 0.57 | | |
| | | Repair to Nahani & W. C. of R/C bldg. known as | | | | Completed | |
| 2010-2011 | MAR | Progressive B at Chinchpokli in E-1 Divn. | 0.59 | 0 | 0.59 | | |
| | | Repair to G.I. Pipe in BMC line of R/C Bldg. Progressive | | | | Completed | |
| 2010-2011 | MAR | C1, C2, B1, B2 in E-1 Divn. | 0.19 | 0 | 0.19 | | |
| | | Repair to Nahani & W.C. of R/C Bldg. known as | | | | Completed | |
| 2010-2011 | MAR | Progressive A at Chinchpokli in E-1 divn. | 0.55 | 0 | 0.55 | | |
| | | Repair to Nahani of R/C Bldg.known as Abhinandan, at | | | | Completed | |
| 2010-2011 | MAR | R.B.Marg in E-1 Divn. | 0.61 | 0 | 0.61 | | |
| 2010-2011 | | Repair to G.I. Pipe and Gate valve in BMC line of the Bldg.known as Sahakar Sadan No.1 & 2 in E-1 Divn. | 0.54 | 0 | 0.54 | Completed | |
| 2010-2011 | | Repair to G.I.Pipe & Gate valve in BMC line of R/C Bldg. known as Ashakunj , Ambika Niwas, Dwarkamai, in E-1 Divn. | 0.52 | 0 | 0.52 | Completed | |
| 2010-2011 | MAR | Providing antitermite treatment to R/C Bldg. known as Abhinandan A wing, at R.B.Marg in E-1 Divn. Through C.R.Fund. | 0.62 | 0 | 0.62 | Completed | |
| | | Repair to G.I. pipe and Gate valve BMC line of R/C bldg. | | | | Completed | |
| 2010-2011 | MAR | known as Indraprasth in E-1 Divn. | 0.46 | 0 | 0.46 | | |
| | | Repair to G.I. Pipe of R/C Bldg. known as Abhinandan in | | | | Completed | |
| 2010-2011 | MAR | Downtake line in E-1 Divn. | 0.55 | 0 | 0.55 | | |
| 2010-2011 | MAR | Providing antitermite treatment to R/C Bldg. known as Abhinandan B-wing at R.B.Marg, in E-1 Divn. | 0.62 | 0 | 0.62 | Completed | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|--|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| | | Repairs to attend UG tank in C I Manhole cover of R/C | | | | Completed | |
| 2010-2011 | MAR | Bldg.known as Indraprasth, Shivdarshan, Telli gully, Astavinayak, Progressive C1, C2, B2 in E-1 Divn. | 0.48 | 0 | 0.48 | | |
| | | | | | | Completed | |
| 2010-2011 | MAR | Repairs to G.I. Pipe and Gate valve in downtake line and loop line of R/C bldg. known as Abhinandan in E-1 Divn. | 0.57 | 0 | 0.57 | | |
| 2010-2011 | MAR | Repairs to G.I. Pipe and gate valve of R/C Bldg. known as Omkar B1, B2 in E-1 Division. | 0.58 | 0 | 0.58 | Completed | |
| 2010-2011 | MAR | Repair to G.I.Pipe and Gate valve of R/C Bldg. known as Omkar A1, A2 in E-1 Divn. | 0.6 | 0 | 0.6 | Completed | |
| 2010-2011 | | Repairs to PVC pipe and cutting down trees of R/C Bldg. known as Vitthal Krupa in E-1 Divn. | 0.16 | 0 | 0.16 | Completed | |
| 2010-2011 | | Repairs to Nahani of R/C Bldg. known as Sahakar Sadan No.1 at Chinchpokli, in E-1 Divn, through C.R.Fund. | 0.62 | 0 | 0.62 | Completed | |
| 2010-2011 | | Repairs to Nahani of R/C Bldg. known as Sahakar Sadan No.2 at Chinchpokli, in E-1 Divn, through C. R. Fund. | 0.62 | 0 | 0.62 | Completed | |
| 2010-2011 | | Providing antitermite treatment to R/C Bldg. known as Dwarkmai & Sai- Krupa in E-1 Divn. Mumbai through C.R.Fund | 0.62 | 0 | 0.62 | Completed | |
| | | C. R. to R/C Bldg. Shirshakti B- wing Telly Gully repair to | | | | Completed | |
| 2010-2011 | MAR | room ceilling with siporex powder in E - 1 ward | 0.57 | 0 | 0.57 | Completed | |
| 2010-2011 | MAR | Providing antitermite treatment to R/C Bldg. known as Ambika Niwas & Vitthal krupa in E-1 Divn. Mumbai | 0.58 | 0 | 0.58 | | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|--|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| | | Attending leakages from room Nahanies of RC bldg. Shiv | | | | Completed | |
| 2010-2011 | MAR | Shakti ,Telli Gulli, in E ward, Mumbai , | 0.59 | 0 | 0.59 | | |
| | | Providing antitermite treatment to R/C Bldg. known as | | | | Completed | |
| 2010-2011 | MAR | Asha Kunj in E-1 Divn. Mumbai | 0.62 | 0 | 0.62 | | |
| | | C. R. to R/C Bldg. Gaodevi Darshan at Mazgaon Dorkyard | | | | Completed | |
| | | road, repair to A & B wing staircase plaster & painting in | | | | | |
| 2010-2011 | MAR | E - 1 ward | 0.47 | 0 | 0.47 | | |
| | | C.R to reconst. Bldg.known as Gondevi Darshan & | | | | In Progress | |
| | | shubhangnam at Mazgaon E ward, providing Rollng | | | | | |
| 2010-2011 | MAR | shutter to shops | 0 | 0 | 0 | LD | |
| | | C.R to reconst. Bldg.known as Sankalp Niketan & Kranti | | | | In Progress | |
| | | Niwas at Mazgaon E ward, providing Rollng shutter to | | | | | |
| 2010-2011 | . MAR | shops | 0 | 0 | 0 | | |
| | | Repairs to Damaged& decayed common meter room | | | | In Progress | |
| | | ,Terrace & Bath door to R/C Bldg Ashakunj & Shivdarshan | | | | | |
| 2010-2011 | . MAR | in E-1 Divn, mumbai | 0 | 0 | 0 | Completed | |
| | | Repairs to Damaged& decayed window shutter to R/C | | | | Completed | |
| | | Bldg known as shivshakti A -wing in E-1 Divn, mumbai | | | | | |
| 2010-2011 | . MAR | through C R fund | 0.62 | 0 | 0.62 | | |
| | | Repairs to Damaged& decayed window shutter to R/C | | | | Completed | |
| | | Bldg known as shivshakti B -wing in E-1 Divn, mumbai | | | | | |
| 2010-2011 | . MAR | through C R fund | 0.61 | 0 | 0.61 | Completed | |
| | | C. R. to R/C Bldg. as Pragati at Noor baug in E-1 Divn, | | | | Completed | |
| | | repair to stair case by providing RCC galli & plaster & | | | | | |
| 2010-2011 | MAR | painting from C.R.fund 2010-2011 | 0.49 | 0 | 0.49 | | |
| | | C.R to reconst. Bldg.known as A1,A2,B1,B2 in E1 | | | | Completed | |
| | | ward, providing M.S grill to staircase duct and terrace open | | C C | | | |
| 2010-2011 | MAR | space from C.R fund 2010-2011 | 0.53 | 0 | 0.53 | | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| 2010-2011 | MAR | Sweeping & Cleaning of R.C Bldg. known as Abhinandan , Pragati, Raje shivaji, Omkar , Sidkrupa, Vithal krupa , Ambika Niwas, Dwarkamai, Ashakunj in E-1 Divn. | 0 | 0 | 0 | In Progress | |
| 2010-2011 | MAR | Sweeping & Cleaning of R.C Bldg. known as Kokan manzil , Durga bhavan, Panchasheal , Rajadasnath, Taqdeer Niwas , Goandas darshan, shubhangam, Sankalp Niketan, Datta Niwas , Audumber, Sahakar Sadan no 1 & 2 in E-1 Divn. | 0 | 0 | 0 | In Progress | |
| 2010-2011 | MAR | Sweeping & Cleaning of R.C Bldg. known as Shivshakti , Shivdarshan, Astavinayak , Progressive A, B,C1,C2 Indraprastha in E-1 Divn. | 0 | 0 | 0 | In Progress | |
| 2010-2011 | MAR | C. R. to R/C Bldg. Ashakunj in E-1 Divn. Attending leakage from room nahanies & WCS | 0.59 | 0 | 0.59 | Completed | |
| 2010-2011 | MAR | C. R. to R/C Bldg. Goandevi darshan in E-1 Divn. Attending leakage from room nahanies & WCS | 0.53 | 0 | 0.53 | Completed | |
| 2010-2011 | MAR | C. R. to R/C Bldg. Indraprasta in E -1 Ward, Repairs to UG tank | 0.61 | 0 | 0.61 | Completed | |
| 2010-2011 | MAR | Repair to G.I. Pipe and Gate value in down take line of R/C bldg. known as Ashakunj in E-1 Divn. | 0.54 | 0 | 0.54 | Completed | |
| 2010-2011 | MAR | C.R.to R/C Bldg. known as Astavinayak A Wing in E- 1ward. Attending leakages of bath | 0.59 | 0 | 0.59 | Completed | |
| 2010-2011 | MAR | C.R.to R/C Bldg. known as Shivdarshan in E-1 ward repair to O.H.tank-2 | 0.52 | 0 | 0.52 | | |
| 2010-2011 | MAR | C.R.to R/C Bldg. known as Dwarkamai at Nariyal Wadi in E-1 repairs to compound wall | 0.62 | 0 | 0.62 | Completed | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|--------------------|---------|
| | | Structure repair for carrying out external plaster & painting | | | | In Progress | |
| 2010-2011 | MAR | work of R/C bldg known as Abhinandan at R.B. marg Mazgaon, in E-1 divn | 0 | 12.82 | 12.82 | | |
| 2010 2011 | | S.R. to R/C bldg known as Kokan manzil at Dockyard | 0 | 12.02 | 12.02 | In Progress | |
| 2010-2011 | MAR | road in E-1 Divn. | 9.13 | 6.3 | 15.43 | | |
| | | Structure repair for carrying out external plaster & painting | | | | Completed | |
| | | work of R/C bldg known as Shivshakti at Teli Gully in E- | | | | | |
| 2010-2011 | MAR | 1 ward | 20.52 | 3.07 | 23.59 | | |
| | | S.R. to internal structural repairs work to R/C bldg known | | | | In Progress | |
| 2010-2011 | MAR | as Indraprasta in E-1 Ward | 13.81 | 0.66 | 14.47 | | |
| | | S.R.to carrying out structural repair work to R/C bldg | | | | In Progress | |
| 2010-2011 | MAR | known as Abhinandan at R.B.marg in E-1 Divn | 0 | 1.72 | 1.72 | | |
| | | S.R. to carrying out structural repair works to R/C bldg known as progressive A,B, C-1,C-2 at D.L.marg in E-1 | | | | In Progress | |
| 2010-2011 | MAR | Divn | 12.79 | 0 | 12.79 | | |
| | | S.R.to carrying out structural repair work to R/C bldg | | | | In Progress | |
| 2010-2011 | MAR | known as Sahakar Sadan no.1 in E-1 Divn | 15.72 | 0 | 15.72 | | |
| | | S.R.to carrying out structural repair work to R/C bldg | | | | In Progress | |
| 2010-2011 | MAR | known as Durga Bhavan 73-77 Mazgaon in E-1 Divn | 9.42 | 0 | 9.42 | | |
| | | Improvement of drainage arrangment & laying rough | | | | In Progress | |
| | | shahabad flooring to R/C bldg known as Audumber in | | | | | |
| 2010-2011 | MAR | E-1divn | 0 | 3.15 | 3.15 | | |
| | | | | | | In Progress | |
| | | S.R.work providing water proofing to terrace & over head | | | | | |
| 2010-2011 | MAR | tank of R/C Bldg known as Shivshakti in E-1 Divn | 0 | 0 | 0 | La Das successions | |
| | | structural repair to R/C bldg known as Sankalp Niketan at | | | | In Progress | |
| 2010-2011 | MAR | Dockyard road in E-1 divn | 0 | 0 | 0 | | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| | | | | | | Completed | |
| 2010 2011 | | structural repair to R.C.C . Member of R/C bldg known as omkar A-1-A-2 & B-1/B-2 at kalachowki in E-1 Divn | 0 | 11.04 | | | |
| 2010-2011 | IVIAR | | 0 | 11.04 | 11.04 | Completed | |
| | | S.R for Improvement of drainage arrangement to R/C bldg gaondevi Darshan, Kranti Niwas & Panchsheel bldg | | | | Completed | |
| 2010-2011 | | in E-1 Divn | 0 | 9.91 | 0.01 | | |
| 2010-2011 | IVIAK | Improvement of drainage arrangment to R/C bldg known | 0 | 9.91 | 9.91 | Completed | |
| 2010-2011 | MAR | as Omkar A-1/A-2,B-1/B-2 in E-1divn | 0 | 7.41 | 7.41 | <u>-</u> | |
| 2010-2011 | | Improvement of drainage arrangment R/C bldg known as | 0 | /. 1 | 7.41 | In Progress | |
| 2010-2011 | MAR | Abhinandan in E-1divn | 0 | 6.63 | 6.63 | C | |
| 2010 2011 | | Improvement of drainage arrangment to R/C bldg known | 0 | 0.05 | 0.05 | In Progress | |
| 2010-2011 | MAR | as Sankalp niketan in E-1divn | 0 | 4.81 | 4.81 | | |
| | | S.R. to carrying out external plaster painting, and internal | | | | In Progress | |
| 2010-2011 | MAR | work at R/C bldg Raja Dashrath in E-1 Divn | 0 | 0 | 0 | | |
| | | | | | | In Progress | |
| | | Improvement of drainage arrangement of laying shabad | | | | | |
| 2010-2011 | MAR | flooring to R/c Bldg. known as Shivshakti in E-1 Divn. | 0 | 0 | 0 | | |
| | | Internal structural repair to R/C bldg. known as | | | | In Progress | |
| 2010-2011 | MAR | Shivdarshan in E-1 Dn. | | 0 | 0 | | |
| | | S.R. to improvement of draingage arrangement to R/C | | | | In Progress | |
| 2010-2011 | MAR | bldg .known as Sahakar Sadan 1 & 2 in E-1 Div. | 0 | 7.43 | 7.43 | | |
| | | | | | | In Progress | |
| | | S.R. to improvement of draingage arrangement to R/C | | | | | |
| 2010-2011 | MAR | bldg .known as Progressive A,B,C1 & C2 in E-1 Div. | 0 | 0 | 0 | | |
| | | Internal structural repair to R/C bldg. known as Astavinayk | | | | In Progress | |
| 2010-2011 | MAR | in E-1 Dn. | 0 | 11.04 | 11.04 | | |
| | | S.R. to Internal structural repair work to R/C bldg. Sahakar | 0 | | | Completed | |
| 2010-2011 | MAR | Sadan No.2, in E-1 Divn. | | 9.4 | 9.4 | | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| | | S.R. to R/C bldg.known as Konkan Manzil in E-1 ward. | 14.04 | | | In Progress | |
| 2010-2011 | MAR | Improvement of Drainage arrangement | 0 | 0 | 14.04 | Completed | |
| | | Repir to G. I. Pipe & Gate valve in pumpline of R/C bldg. | 0 | 0 | | Completed | |
| 2010-2011 | MAR | known as Pansheel in E-1 Div. | 0.56 | 0 | 0 | Completed | |
| | | C. D. to D/C bldg known og sbivebakti D.Wing in E. 1divn | 0.50 | | | Completed | |
| 2040 2044 | | C.R. to R/C bldg known as shivshakti B Wing in E-1divn. P/F staircase treads & risers kotah stone flooring | | 0 | 0.50 | | |
| 2010-2011 | IVIAR | Repair to PVC pipe & cutting down trees of R/C Bldg. | 0.62 | 0 | 0.56 | Completed | |
| 2010 2011 | | known as pragati in E-1 divn. | 0.02 | 0 | 0.02 | Completed | |
| 2010-2011 | IVIAK | C.R. To R/C bldg Abhinandan in E-1, Repair to DH tank | 0.39 | 0 | 0.62 | Completed | |
| 2010-2011 | | | 0.03 | 0 | 0.39 | Comprova | |
| 2010-2011 | IVIAN | C.R. to R/C bldg Indraprasta in E-1 din. Attending | 0.6 | 0 | 0.59 | Completed | |
| 2010-2011 | MAR | leakages O.H.Tank no. 1 | | 0 | 0.6 | <i>F</i> | |
| 2010 2011 | | C.R. to R/C Bldg Astavinayak to E-1 ward Attending | 0.55 | Ū | 0.0 | Completed | |
| 2010-2011 | MAR | leakages of O.H.W.Tank no. 1 | | 0 | 0.55 | L L | |
| 2010 2011 | | C.R.To R/C bldg known as Shivshakti C-Wing in E-1 P/F | 0.61 | Ŭ | 0.00 | Completed | |
| 2010-2011 | MAR | treads & risers kotah stone Flooring | | 0 | 0.61 | - | |
| | | | 0.62 | | 0.01 | Completed | |
| | | Repairs to CI manhaole cover of O.H.W.T & U.G.W.T Of | | | | | |
| | | R/C bldg kokan manzil, Sankalpa Niketan, Gavdevi | | | | | |
| | | Darshan, Kranti Niwas, Shubhangan Raja Dashrath, | | | | | |
| 2010-2011 | MAR | Taqdeer Niwas in E-1 divn. | | 0 | 0.62 | | |
| | | Repairs to PVC pipe and cutting down trees of R/C Bldg | 0.57 | | | Completed | |
| 2010-2011 | MAR | known as Raja Shivaji in E-1 Divn. | | 0 | 0.57 | | |
| | | Repair to CI manhole cover of OHWT & UGWT Of R/C | 0.62 | | | Completed | |
| | | bldg known as Vithal Krupa, Saikrupa, Dwarka mai, | | | | | |
| | | Ambika Niwas, Ashakunj, Audumber, Pragati, Puncsheel | | | | | |
| 2010-2011 | MAR | in E-1 Din. | | 0 | 0.62 | | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| | | Repairs to PVC pipe & cutting down trees of R/C bldg | 0.57 | | | Completed | |
| 2010-2011 | MAR | known as Saikrupa in E-1 Din. | | 0 | 0.57 | | |
| | | C.R. To R/C bldg Dwarkamai at Nariyalwadi in E-1 | 0.37 | | | Completed | |
| | | Improvement to plinth proteetien with rough shahabad | | | | | |
| 2010-2011 | MAR | flooring. | | 0 | 0.37 | | |
| | | C.R. to R/C bldg progressive A-1, B-1 & C1,C2 in E-1 | 0.62 | | | Completed | |
| | | divn. Replacement of decayed door & frame of H.R. pump | | | | | |
| 2010-2011 | MAR | room & M.R. | | 0 | 0.62 | | |
| | | C.R. to R/C bldg Sankalp Niketan in E-1 Din. Repairs to | 0.59 | | | Completed | |
| 2010-2011 | MAR | WC (B Wing) | | 0 | 0.59 | | |
| | | Repairs to PVC Pipe & cutting down trees to R/C bldg | 0.51 | | | Completed | |
| 2010-2011 | MAR | known as Dwarkamai in E-1 Din | | 0 | 0.51 | | |
| | | C.R. ToR/C bldg Omkar B-1 & B-2 in E-1 Din. Attending | 0.38 | | | Completed | |
| 2010-2011 | MAR | leakages of U.G.tank | | 0 | 0.38 | | |
| | | C.R. to R/C Bldg Astavinayak B-Wing in E-1 ward | 0.6 | | | Completed | |
| 2010-2011 | MAR | Attending leakages of bath | | 0 | 0.6 | | |
| | | Repair to PVC pipe & cutting down trees of R/C Bldg. | 0.56 | | | Completed | |
| 2010-2011 | MAR | known as Ambika Niwas in E-1 divn. | | 0 | 0.56 | | |
| | | Replacement of decayed common WC door & frame of | 0.36 | | | Completed | |
| 2010-2011 | MAR | R/C bldg Raje Shivaji -B wing in E-1 Divn. | | 0 | 0.36 | | |
| | | Repair to PVC Pipe & Cutting down trees of R/C Bldg | 0.59 | | | Completed | |
| 2010-2011 | MAR | known as Ashtavinayak in E-1 Divn. | | 0 | 0.59 | | |
| | | C.R. to R/C Bldg Astavinayak in E-1 ward Attending | 0.55 | | | Completed | |
| 2010-2011 | MAR | leakages of U.G.tank | | 0 | 0.55 | | |
| | | Replacement of decayed common wc door and frame of | 0.62 | | | Completed | |
| 2010-2011 | MAR | R/C bldg Raje Shivaji A wing in E-1 Din. | | 0 | 0.62 | | |
| | | Repair to PVC pipe & cutting down trees of R/C bldg | 0.48 | | | Completed | |
| 2010-2011 | MAR | progressive C-1 in E-1Divn. | | 0 | 0.48 | | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| | | C.R. To R/C bldg Raja Dasharath in E-1 Din. Repairs to | 0.34 | | | Completed | |
| 2010-2011 | l MAR | drainage system | 0.5 | 0 | 0.34 | Completed | |
| | | Repair to door and window to R/C bldg known as Taqdeer Niwas of Mazgaon in E-1 Din. Through C.R.fund 2010- | 0.5 | | | Completed | |
| 2010-2011 | | 2011 | | 0 | 0.5 | | |
| 2010-2011 | | Repairs to PVC pipe & cutting down trees of R/C bldg | 0.18 | 0 | 0.5 | Completed | |
| 2010-2011 | L MAR | knwn as Ashakunj in E-1 Ward | | 0 | 0.18 | - | |
| | | C.R. to R/C bldg Sankalp Niketan in E-1 Din. Repairs to | 0.46 | | | Completed | |
| 2010-2011 | L MAR | Bath(B Wing) | | 0 | 0.46 | | |
| | | C.R. to cleaning & Washing UG tank & OH water from | 0.49 | | | Completed | |
| 2010-2011 | L MAR | inside of R/C bldg in E-1 Divn. | | 0 | 0.49 | | |
| | | C.R to R/C bldg Sankalp Niketan in E-1 din. Replacement | 0.6 | | | Completed | |
| | | decayed door & frame & shutter of H.R. meter room | | | | | |
| 2010-2011 | l MAR | pump bldg. | 0.52 | 0 | 0.6 | 0 141 | |
| | | Repair to PVC pipe & cutting down trees of R/C bldg | 0.52 | | | Completed | |
| 2010-2011 | l MAR | Brama Indraprastha In E-1 Din. | 0.61 | 0 | 0.52 | Completed | |
| | | Repair to CI manhole cover of OHWT & UGWT Of R/C bldg known as Omkar A-1, A-2, B-1, B-2 , Abhinandan , | 0.01 | | | completed | |
| 2010-2011 | MAR | Durga Bhavan in E-1 Din. | | 0 | 0.61 | | |
| 2010 2011 | | C.R. to R/C bldg Omkar A-1,A-2,B-1,B-2, In E-1 Divn. | 0.57 | v | 0.01 | Completed | |
| | | Replacement door and frame shutter H.P meter room & | | | | | |
| 2010-2011 | L MAR | pump room | | 0 | 0.57 | | |
| | | Repair to PVC pipe & cutting down trees of R/C bldg | 0.59 | | | Completed | |
| 2010-2011 | L MAR | Omkar A-1 IN E-1 Divn. | | 0 | 0.59 | | |
| | | C.R to R/C Bldg Omkar A1 & Omkar A2 in E-1 Divn. | 0.41 | | | Completed | |
| 2010-2011 | L MAR | Repair to UG Tank | | 0 | 0.41 | | |
| | | Repair to PVC pipe & cutting down small trees of R/C Bldg | 0.59 | | | Completed | |
| 2010-2011 | L MAR | Audumber in E-1 divn. | | 0 | 0.59 | | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| | | C.R. To R/C bldg Raja Dasharath in E-1 Din.attending | 0.43 | | | Completed | |
| 2010-2011 | MAR | leakages of OH tank | 0.42 | 0 | 0.43 | | |
| 2010-2011 | MAR | Repair to PVC pipe & small trees cutting of R/C bldg Shubhangam in E-1 Divn. | 0.42 | 0 | 0.42 | Completed | |
| | | CR to R/C bldg Kokan Manzil in E-1 Divn. Providing | 0.39 | | | In Progress | |
| 2010-2011 | MAR | Antitermite treatment. | | 0 | 0.39 | | |
| | | Repair to PVC pipe & cutting down small trees of R/C Bldg | 0 | | | Completed | |
| 2010-2011 | MAR | progressive A in E-1 divn. | | 0 | 0 | | |
| | | C.R To R/C Bldg Ashtavinayak in E-1 Ward . Repair to OH | 0.33 | | | Completed | |
| 2010-2011 | MAR | Tank no. 2 | | 0 | 0.33 | | |
| | | C.R. to R/C bldg known as Durga Niwas in E-1 Ward | 0.61 | | | In Progress | |
| 2010-2011 | MAR | providing Anti termite treatment | | 0 | 0.61 | | |
| | | C.R. to R/C bldg Indraprasta in E-1 din.Repair to | 0 | | | Completed | |
| 2010-2011 | MAR | O.H.Tank no. 1 | | 0 | 0 | | |
| | | Repair to PVC pipe and cutting down trees of R/C Bldg | 0.56 | | | Completed | |
| 2010-2011 | MAR | known as Omkar B-1 In E-1Divn. | | 0 | 0.56 | | |
| | | Repair to PVC pipe and cutting down trees of R/C Bldg | 0.42 | | | Completed | |
| 2010-2011 | MAR | known as progressive C-2 In E-1Divn. | | 0 | 0.42 | | |
| | | | 0.35 | | | Completed | |
| | | C.R to R/C bldg known as Shivshakti A & B Wing in E-1 | | | | | |
| | | Divn. Replacement of decayed common WC door and | | | | | |
| 2010-2011 | MAR | frames through CR. Fund for the year 2010-11 | | 0 | 0.35 | | |
| | | C.R. to R/C bldg known as Ambika Niwas in E-1 Ward | 1.23 | | | Completed | |
| | | Improvement of Drainage arrangement through CR fund | | | | | |
| 2010-2011 | MAR | for the year 2010-11 | | 0 | 1.23 | | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|--|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| | | C.R to R/C bldg known as Sahakar sadan bldg no. 1 in E- 1 Divn. Replacement of decayed common WC door and | 0 | 1.00 | | Completed | |
| 2010-2011 | MAR | frames through CR. Fund for the year 2010-11 | 0 | 1.23 | 1.23 | Completed | |
| 2010-2011 | MAR | Inside water proofing to U.G tank of R/C bldg known as Sahakar Sadan no. 1 in E-1 divn. Through CR fund | Ū | 0 | 0 | Completed | |
| 2010-2011 | MAR | Repair to R/C pipe and cutting down trees of R/C bldg known as Omkar A-2 in E-1 Divn. | 1.24 | 0 | 1.24 | Completed | |
| 2010-2011 | MAR | Repair to PVC pipe and cutting down trees of R/C Bldg known as Omkar B-2 in E-1 Divn. | 0.41 | 0 | 0.41 | Completed | |
| 2010-2011 | MAR | C.R. to R/C bldg known as Panchsheel in E ward providing Antitermite treatement | 0.43 | 0 | 0.43 | In Progress | |
| 2010-2011 | MAR | Repair to pipe support for terrace GI Pipe of R/C Bldg Indraprashta in E-1 Divn. | 0 | 0 | 0 | Completed | |
| 2010-2011 | MAR | Repair to PVC pipe & cutting down trees of bldg known as Progressive -B in E-1 Divn. | 0.55 | 0 | 0.55 | Completed | |
| 2010-2011 | MAR | C.R. to R/C bldg known as Dwarkamai at Nariyalwadi in E- 1 Divn. Repairs to D.H.W Tank | 0.34 | 0 | 0.34 | In Progress | |
| 2010-2011 | MAR | C.R. to R/C bldg known as Shubhangam in E-1 Divn. Repairs to O.H . Tank | 0 | 0 | 0 | In Progress | |
| 2010-2011 | MAR | C.R. to R/C bldg Abhinandan in E-1, Divn. Repairs to O.G.Tank | 0 | 0 | 0 | Completed | |
| 2010-2011 | MAR | C.R to R/C bldg Raja Shivaji A Wing in E-1 din. Attending leakages through WC. | 0.61 | 0 | 0.61 | In Progress | |
| 2010-2011 | | C.R. To R/C bldg Ambika Niwas at Nariyalwadi in E-1 Din. Repair to O.H.W.tank | 0 | 0 | 0 | In Progress | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| 2040 2044 | | C.R. to R/C bldg Raja Shivaji wing B in E-1 Divn. | 0 | 0 | | In Progress | |
| 2010-2011 | MAR | Attending leakages through W.C. | 0 | 0 | 0 | In Progress | |
| 2010-2011 | MAR | C.R. to repair to pipe support for terrace GI pipe of R/C Bldg known as Gavdevi darshan kranti niwas in E-1 Divn., | Ū | 0 | 0 | 1111021055 | |
| 2010-2011 | MAR | Repair to GI pipe gate valve in down take line and loop line of R/C Bldg known as kokan manzil in E-1 | 0 | 0 | 0 | In Progress | |
| 2010-2011 | MAR | Repair to GI Pipe & gate valve in down take line & loop line to R/C bldg Omkar A-2 in E-1 Divn. | 0 | 0 | 0 | In Progress | |
| 2010-2011 | MAR | C.R. to R/C bldg Sankalp Niketan in E-1 divn. Attending leakages of O.H.Tank | 0 | 0 | 0 | Completed | |
| 2010-2011 | MAR | Proposal renovation of office of Ex. Enp E-1 / Kalachowki Mumbai-33 | 1.3 | 3.73 | 5.03 | In Progress | |
| 2010 2011 | MAD | C.R. to R/C bldg known as Sahakar Sadan NO.2 in E-1 Ward replacement of decayed common WC door and shutters | 0 | 0 | 0 | In Progress | |
| 2010-2011 | . WAR | C.R. toR/C bldg Sankalp Niketan in E-1 Ward repair to | 0 | 0 | 0 | In Progress | |
| 2010-2011 | MAR | U.G. Tank (A and B wing) | | 0 | 0 | | |
| 2010-2011 | MAR | Repairs to GI Pipe and gate valve in down take and loopline of R.C bldg known as Omkar B-2 in E-1 Divn. | 0 | 0 | 0 | In Progress | |
| 2010-2011 | MAR | Repairs to Pipe support for terrace GI pipe of R/C bldg Sahakar Sadan -2 in E-1 Divn. | 0 | 0 | 0 | In Progress | |
| 2010-2011 | MAR | C.R. to R/C building Shivdarshan in E-1 divn. Attending leakages O.H.Tank no. 1 | 0 | 0 | 0 | In Progress | |
| 2010-2011 | MAR | C.R. to R/C bldg nkown as Raja Shivaji wing A1 and B1 wing in (E-1 Divn.)Attending leakages of bath | 0 | 1.32 | 1.32 | Completed | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|--------|---|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| | | C.R. to R/C bldg known as Abhinandan replacement of | 0 | | | In Progress | |
| 2010-2011 | MAR | damaged decayed common toilet door through C.R. fund for the year 2010-2011 | | 0 | 0 | | |
| 2010 2011 | | C.R. to R/C bldg Sankalp Niketan attending leakages of | | Ŭ | 0 | Completed | |
| 2010-2011 | L MAR | W.C and bath (wing A) | 0 | 1.22 | 1.22 | | |
| | | | | | | Completed | |
| | | C.R. to R/C bldg known as Audumber A and B wing repair | | | | | |
| 2010-2011 | L MAR | to O.H.W tank no 1 and 2 through C.R. fund 2010-2011 | 0 | 1.28 | 1.28 | Completed | |
| 2010 2011 | | C.R. to R/C bldg known as Sahakar sadan bldg no. 2 repair to O.H.W. tank no 1 through C.R. fund | 0 | 1.31 | 1.21 | Completed | |
| 2010-2011 | LIVIAR | Enternal repairs to water tank of R/C bldg known as | 0 | 1.51 | 1.31 | In Progress | |
| 2010-2011 | L MAR | Sahakar Sadan no. 1 Through C.R. fund | 0 | | 0 | | |
| | | Repairs to G.I. pipe gate volve in down take line, loopline pumpline of R/C bldg known as Shivshakti A,B,C in E-1 | | | | In Progress | |
| 2010-2011 | MAR | divn. | 0 | 0 | 0 | | |
| | | Densiste C. L. size sete value is DMC line, superline and | | | | Completed | |
| 2010-2011 | | Repair to G.I. pipe gate valve in BMC line, pumpline and down take line of R.C. bldg known as Indraprastha | 0 | 1.23 | 1.23 | | |
| 2010-2011 | | C.R. to R/C bldg Omkar B-2 in E-1 divn. Attending | 0 | 1.25 | 1.25 | In Progress | |
| 2010-2011 | L MAR | leakages of O.H.Tank | 0 | 0 | 0 | | |
| | | | | | | In Progress | |
| | | Repair to G.I pipe and Gate valve in down take line and | | | | | |
| 2010-2011 | MAR | loopline of R/C Bldg known as Durga Bhavan in E-1 divn. | 0 | 0 | 0 | LD | |
| | | Repair to pipe support for treeace GI pipe of R/C bldg | <u>_</u> | | | In Progress | |
| 2010-2011 | MAR | Sahakar Sadan-1 in E-1 divn. | 0 | 0 | 0 | In Progress | |
| | | Repairs to GI pipe and gate valve in down take line and | | | | | |
| 2010-2011 | MAR | loopline of RC bldg known as Omkar B-1 in E-1 Divn. | 0 | 0 | 0 | | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|-------------------------|---------|
| 2010-2011 | MAR | Repairs to GI pipe , gate valve in down take line and loop line of RC bldg known as Kranti Niwas in E-1 Divn. | 0 | 0 | 0 | In Progress | |
| 2010-2011 | MAR | Repairs to pipe support for terrace GI Pipe of R/C bldg known as Rajashivai , Sankalp Niketan in E-1 Divn. | 0 | 0 | 0 | In Progress | |
| 2010-2011 | MAR | Repairs to GI pipe and gate valve in down take and loop line of RC bldg known as Omkar A-1 in E-1 Divn. | 0 | 0 | 0 | In Progress | |
| 2010-2011 | MAR | C.R. to RC bldg Shivdarshan in E-1 divn. Repairs to UG tank and pumproom | 0 | 0 | 0 | In Progress | |
| 2010-2011 | MAR | Repairs to pipe support for terrace GI pipe to R/C bldg Omkar A-1 in E-1 Divn. | 0 | 0 | 0 | In Progress In Progress | |
| 2010-2011 | MAR | Repairs to PVC pipe & cutting down trees of R/C Bldg Shivdarshan in E-1 Divn. | 0 | 0 | 0 | In Progress | |
| 2010-2011 | MAR | Repairs to pipe support for treeace GI pipe & RC bldg known as Omkar A2 In E-1 Divn. | 0 | 0 | 0 | In Progress | |
| 2010-2011 | MAR | Repair to pipe support for terrace GI pipe of R/C bldg Omkar B-2, in E-1 Divn. | 0 | 0 | 0 | In Progress | |
| 2010-2011 | MAR | Repair to GI pipe & gate valve in down take line & loop line & RC bldg Kranti Niwas in E-1 Divn. | 0 | 0 | 0 | In Progress | |
| 2010-2011 | MAR | Repair to PVC pipe & cutting down trees of R/C bldg Gaodevi Darshan in E-1 Divn. | 0 | 0 | 0 | In Progress | |
| 2010-2011 | MAR | Repairs to GI pipe Gate valve in down take line and loopline of RC bldg known as Audumber in E-1 divn. | 0 | 0 | 0 | III FIOgless | |
| 2010-2011 | MAR | Repairs to pipe support for terrace GI pipe of RC bldg Ashtavinyak in E-1 Divn. | 0 | 0 | 0 | In Progress | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| | | | | | | In Progress | |
| | | Repairs to GI pipe , gate valve in down take line and loop | | | | | |
| 2010-2011 | MAR | line of Rc bldg known as Shubhangan in E-1 Divn. | 0 | 0 | 0 | La Dra casas | |
| | | C.R. to R.C bldg Progressive A, C1,C2, in E-1 Divn. | | | | In Progress | |
| | | Replacement of decayed door , frame and shutter of | | | | | |
| 2010-2011 | MAR | common W.C. | 0 | 0 | 0 | La Dra ances | |
| | | Repairs to GI pipe , gate valve in down take line and loop | | | | In Progress | |
| 2010-2011 | MAR | line of RC bldg known as Pragati in E-1 Divn. | 0 | 0 | 0 | La Dro ortogo | |
| | | Repairs To pipe support for terrace GI pipe of RC bldg | | | | In Progress | |
| 2010-2011 | MAR | known as Omkar B in E-1 Divn. | 0 | 0 | 0 | Commisted | |
| | | C.R. To R/C bldg known as Sahakar Sadan bldg no 1 in E- | | | | Completed | |
| 2010-2011 | MAR | 1 Divn. Repairs to O.H. W. tank no 1 | 0 | 1.3 | 1.3 | Completed | |
| | | Repairs to GI pipe, Gate valve in down take line, loop line | | | | Completed | |
| | | pumpline and B MC line of RC bldg known as Sankalp | | | | | |
| 2010-2011 | MAR | Niketan A,B,In E-1 Divn. | 0 | 1.27 | 1.27 | | |
| | | Repairs to GI pipe, Gate valve in down take line, loop line | | | | Completed | |
| | | pumpline of RC bldg known as Ashtavinayak A,B Wing In | | | | | |
| 2010-2011 | MAR | E-1 Divn. | 0 | 1.24 | 1.24 | Completed | |
| | | Repairs to GI pipe, Gate valve in down take line, loop line | | | | Completed | |
| | | pumpline and B MC line of RC bldg known as Rajashivaji | | | | | |
| 2010-2011 | MAR | In E-1 Divn. | 0 | 1.23 | 1.23 | La Dressana | |
| | | C.R to R/C bldg Abhinandan in E-1 ward attending | | | | In Progress | |
| 2010-2011 | MAR | leakages of O.H.Water tank no 1,2 | 0 | 0 | 0 | Completed | |
| | | C.R To R/C bldg Saikrupa in E-1 divn. Repairs to House | | 0 = 0 | | Completed | |
| 2010-2011 | MAR | gully | 0 | 0.78 | 0.78 | Completed | |
| | | Repairs to GI pipe, Gate valve in down take line, loop | | | | Completed | |
| | | line and pumpline of R/C bldg known as Sahakar Sadan In | | | | | |
| 2010-2011 | MAR | E-1 ward | 0 | 1.23 | 1.23 | | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|--|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| | | Repairs C.R. to R/C bldg Ashtakunj in E-1 Ward repairs to | | | | Completed | |
| 2010-2011 | L MAR | Drainage system | 0 | 1.31 | 1.31 | | |
| | | Repairs to GI pipe, gate valve, in down take, line, | | | | Completed | |
| | | loopline and pumpline of R/C bldg known as Sahakar | | | | | |
| 2010-2011 | L MAR | Sadan 2 in E-1 divn | 0 | 1.23 | 1.23 | Consultat | |
| | | Repairs to GI pipe , gate valve , in down take , line , | | | | Completed | |
| | | loopline and pumpline of R/C bldg known as Gaodevi | | 1.00 | | | |
| 2010-2011 | L MAR | Darshan in E-1 divn | 0 | 1.23 | 1.23 | Completed | |
| | | C.R. to R/C bldg progressive A,B and C1,C2 in E-1 divn. | 0 | 1.15 | 4.45 | Completed | |
| 2010-2011 | LMAR | Repairs to common WC | 0 | 1.15 | 1.15 | Completed | |
| | | Repairs to GI pipe , gate valve , in down take , line , | | | | completed | |
| 2010 2011 | | loopline and pumpline of R/C bldg known as Panchsheel A,B In E-1 divn | 0 | 0.00 | 0.00 | | |
| 2010-2011 | LIMAR | C.R. to R/C bldg Ashtavinayak in E-1 Division repair to | 0 | 0.99 | 0.99 | Completed | |
| 2010-2011 | | Chamber | 0 | 0.98 | 0.98 | Compieteu | |
| 2010-2011 | | Sweeping and cleaning work of R/C bldg known as | 0 | 0.98 | 0.98 | Completed | |
| | | Shivshakti, Shivdarshan, Ashtavinayak, Progressive A, B, C, | | | | r r | |
| 2010-2011 | MAR | and C2, Indraprastha in E-1, ward. | 0 | | 0.62 | | |
| 2010 2011 | | | 0 | 0.38 | 0.02 | Completed | |
| | | Raja Dashrath, Kranti Niwas , Taqdeer Niwas, Gaodevi | | | | * | |
| | | Darshan, ,Shubhangam, Sankalp Niketan, Datta niwas, | | | | | |
| 2010-2011 | MAR | Audumber, Sahakar sadan no 1 and 2 for the period | 0 | | 0.38 | | |
| | | C.R. to R/C bldg gaondevi darshan and subhanjan in E-1 | | 0.6 | | Completed | |
| | | Divn. Replecement of decayad door frame and shutter of | | | | | |
| 2010-2011 | MAR | HR, Pump room and meter room | 0 | | 0.6 | | |
| | | C.R. to R/C bldg Raja Dashrath in E-1 Divn. Replecement | | 0.29 | | Completed | |
| | | of decayad door frame and shutter of HR, Pump room and | | | | | |
| 2010-2011 | L MAR | meter room | 0 | | 0.29 | | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|---------|--|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| | | C.R. to R/C. bldg Sankalp Niketan in E-1 Divn. Attending | | 0.62 | | Completed | |
| 2010-2011 | . MAR | leakages or U.G.Tank | 0 | 0.52 | 0.62 | | |
| | | C.R. To R/C bldg Indraprastha in E-1 Divn. Replacement | | 0.53 | | Completed | |
| | | or decayed door shutter frame or HR merer room and | | | | | |
| 2010-2011 | MAR | pump room | 0 | 0.62 | 0.53 | Completed | |
| | | C.R. to R/C bldg Dwarka Niwas in E-1 divn. Replacement | | 0.02 | | Completed | |
| | | of decayed door shutter and frame or HR and pump , | 0 | | | | |
| 2010-2011 | . MAR | meter room and w.c. | 0 | 0.39 | 0.62 | Completed | |
| | | C.R. to R/C bldg Taqdeer Niwas in E-1 Divn. Repairs to | 0 | 0.39 | | Completed | |
| 2010-2011 | . MAR | House gully and compound wall | 0 | 0.61 | 0.39 | Completed | |
| | | C.R. To R/C bldg Saikrupa in E-1 Divn. Replacement of | | 0.01 | | Completed | |
| 2010 2011 | | decayed door frame and shutter of common w.c. pump room and new room | 0 | | 0.61 | | |
| 2010-2011 | . MAR | | 0 | 0.41 | 0.61 | Completed | |
| | | C.R. to Vitthal Krupa in E-1 Divn. Replacement of decayed | | 0.41 | | Completed | |
| 2010 2011 | | door frame and shutter of meter room pump room and | 0 | | 0.41 | | |
| 2010-2011 | . IVIAK | new room Providing antitermin treatmant to R/C bldg known as | 0 | 0.62 | 0.41 | Completed | |
| | | Sankalp Niketan, A Wing, in E-1, Divn. Mumbai through | | 0.02 | | Compieteu | |
| 2010-2011 | | C.R. fund | 0 | | 0.62 | | |
| 2010-2011 | | C.R. to R/C bldg Shivdarshan in E-1 Divn. Replacement of | | 0.45 | 0.02 | Completed | |
| | | decayed door frame and shutter or pump room , meter | | | | L L | |
| 2010-2011 | MAR | room and new room | 0 | | 0.45 | | |
| 2010 2011 | | C.R. to R/C bldg Ambika Niwas in E-1 Divn. Replacement | 0 | 0.6 | 0.13 | Completed | |
| | | of decayed door frame and shutter or pump room , meter | | | | - | |
| 2010-2011 | MAR | room and w.c. | 0 | | 0.6 | | |
| | | Providing antitermin treatmant to R/C bldg known as 7,9 | | 0.37 | 510 | Completed | |
| | | Raja Dashrath at brahmadev khat road in E-1, Divn. | | | | | |
| 2010-2011 | MAR | Mumbai through C.R. fund | 0 | | 0.37 | | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|--|-----------------------------------|------------------------------------|----------------------|------------------|---------|
| | | C.R. to R/C bldg kranti Niwas in E-1 Divn. Replacement of | | 0.56 | | Completed | |
| | | decayed door frame and shutter or pump room , meter | | | | | |
| 2010-2011 | MAR | room and w.c. | 0 | | 0.56 | | |
| | | C.R. to R/C bldg Saikrupa in E-1 Divn. Replacement of | | 0.15 | | Completed | |
| | | decayed door frame and shutter or pump room , meter | | | | | |
| 2010-2011 | MAR | room and w.c. | 0 | | 0.15 | | |
| | | Proposed renovation of office of Executive Eng. E-1 Divn. | | | | In Progress | |
| 2010-2011 | MAR | Kalachowki, Mumbai-33 furniture work. | 0 | 3.85 | 3.85 | | |
| | | Islamiya Manzil, Rangari Street (Repairs to terrace, water | | | | | |
| 2010-2011 | MAR | proofing, O.H & U.G tank) | 0 | 2.55 | 2.55 | Work In Progress | |
| | | Mombattiwala, 47/51 (Repair to room ceilling / beam | | | | | |
| 2010-2011 | MAR | plastering) | 0.61 | 0 | 0.61 | Work In Progress | |
| | | Mombattiwala, 47-51 (Repairs to waterproffing to W.C.R | | | | | |
| 2010-2011 | MAR | bath & leakages) | 0.6 | 0 | 0.6 | Work In Progress | |
| | | Mombatttiwala 47-51, Umer Rajjab Road (Repair to | | | | | |
| 2010-2011 | MAR | drainage pipe line) | 0.58 | 0 | 0.58 | Work In Progress | |
| 2010-2011 | MAR | Shivneri (Providing rough S.S.flooring) | 0.61 | 0.35 | 0.96 | Work In Progress | |
| 2010-2011 | MAR | Hanuman Prasad (Providing weather shed) | 0.62 | 0 | 0.62 | Work In Progress | |
| 2010-2011 | MAR | Shivneri (Providing weather shed) | 0.58 | 0 | 0.58 | Work In Progress | |
| | | | | | | | |
| 2010-2011 | | Hanuman Prasad (Repair common toilet &toilet shutter) | 0.51 | 0 | 0.51 | Work In Progress | |
| 2010-2011 | | Gulshan Umer (Internal & external plaster painting) | 7.76 | 1.78 | 9.54 | Work In Progress | |
| 2010-2011 | | Jagat Smruti, Gurusadan, Mandar niketean, Gharkul | 0.31 | 0 | 0.31 | Work In Progress | |
| 2010-2011 | MAR | Mombattiwala bldg (Repair to G.I.Pipe) | 0.3 | 0 | 0.3 | Work In Progress | |
| | | Islamai, Ashrafi, Idaeal, Mkka Manzil, Aqsa Manzil, | | | | | |
| 2010-2011 | MAR | Navbahar, Rahmat Manzil | 0.62 | 0 | 0.62 | Work In Progress | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|------------------|---------|
| | | Prabhu Niwas, Bhairwnath, Ratan Sadan, Shivdarshan, | | | | | |
| | | Saikripa, Sai Sadan, Mahalaxmi Sadan, Priyadarshini, Punarjeeven, Kranti Sadan, Gulshan Umer, Mumtaj Mhal, | | | | | |
| 2010-2011 | MAR | Haidari Manzil | 0.62 | 0.3 | 0.92 | Work In Progress | |
| | | R/c bldg of N. M. Jodhi Marg (Attending leakages of PVC | | | 0.01 | | |
| 2010-2011 | MAR | Pipe) | 0.59 | 0 | 0.59 | Work In Progress | |
| | | | | | | | |
| 2010-2011 | MAR | R/c bldg of Saat Rasta (Attending leakages of PVC Pipe) | 0.59 | 0 | 0.59 | Work In Progress | |
| 2040 2044 | | P/o bldg of Pokri Adda (Attending lookages of D)/C Bino) | 0.59 | 0.5 | 4.00 | | |
| 2010-2011 | MAR | R/c bldg of Bakri Adda (Attending leakages of PVC Pipe) | 0.59 | 0.5 | 1.09 | Work In Progress | |
| 2010-2011 | MAR | R/c bldg of Sunder Galli (Attending leakages of PVC Pipe) | 0.59 | 0 | 0.59 | Work In Progress | |
| | | C.R. to replacement of decayed window shutter of R/c | | | | | |
| 2010-2011 | MAR | bldg 'Shivneri' in 'E-2' Ward | 0.50 | 0 | 0.5 | Work In Progress | |
| | | C.R. to replacement of damaged decayed window of R/c | | | | | |
| 2010-2011 | MAR | bldg 'Shivneri' in 'E-2' Ward | 0.49 | 0.5 | 0.99 | Work In Progress | |
| 2010 2011 | | C.R. to replacement of damaged decayed window of R/c | 0.54 | | 0.74 | | |
| 2010-2011 | MAR | bldg 'Mumtaz Mahal' in 'E-2' Ward C.R. to R/c bldg 'Al- Khaiber' Repairs to drainage | 0.54 | 0.2 | 0.74 | Work In Progress | |
| 2010-2011 | MAR | inspection | 0.39 | 0 | 0.39 | Work In Progress | |
| 2010 2011 | | C.R. to R/c bldg 'Hanuman Prasad' Replacement of | 0.00 | | 0.00 | | |
| 2010-2011 | MAR | G.I.Pipe | 0.22 | 0 | 0.22 | Work In Progress | |
| 2010-2011 | MAR | S.R. to R/c bldg 'Ideal Apartment" | 9.65 | 0 | 9.65 | Work In Progress | |
| 2010-2011 | MAR | Prabhu Niwas (Structural rapairs) | 10.02 | 0 | 10.02 | Work In Progress | |
| 2010-2011 | | Islamiya Manzil (Repair to G.I. pipe & gate valves) | 0.54 | 0 | 0.54 | Work In Progress | |
| 2010-2011 | | C.R. to R/c bldg 'Kranti Sadan' in 'E-2' Ward | 0.23 | 0 | 0.23 | • | |
| 2010-2011 | MAR | Islamiya (Repair to G.I. pipe & gate valve) | 0.54 | 0 | 0.54 | Work In Progress | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|--|-----------------------------------|------------------------------------|----------------------|------------------|---------|
| 2010-2011 | . MAR | Navbahar (Repair to G.I. pipe, Gate valve & PVC pipe) | 0.57 | 0 | 0.57 | Work In Progress | |
| 2010-2011 | | C.R. to R/c bldg 'Arunodaya Niwas' in 'E-2' Ward | 0.12 | 0 | 0.12 | Work In Progress | |
| 2010-2011 | MAR | C.R. to R/c bldg 'Sarovar' in 'E-2' Ward | 0.20 | 0 | 0.2 | Work In Progress | |
| 2010-2011 | | Haidari manzil (Attending leakages to O.H tank) | 0.49 | 0 | 0.49 | Work In Progress | |
| 2010-2011 | MAR | C.R. to R/c bldg 'Shivneri' in 'E-2' Ward | 0.49 | 0 | 0.49 | Work In Progress | |
| 2010-2011 | | C.R. to R/c bldg 'Shivneri' & 'Ratan Sadan' in 'E-2' Ward | 0.51 | 0 | 0.51 | Work In Progress | |
| 2010-2011 | MAR | C.R. to R/c bldg 'Shivneri' in 'E-2' Ward | 0.50 | 0 | 0.5 | Work In Progress | - |
| 2010-2011 | MAR | C.R. to R/c bldg 'Sarovar' in 'E-2' Ward | 0.23 | 0 | 0.23 | Work In Progress | |
| 2010-2011 | MAR | S.R. to R/c bldg 'Aqsa Manzil', 'Shivdarshan' & 'Ratan Sadan' in 'E-2' Ward | 6.05 | 0 | 6.05 | Work In Progress | |
| 2010-2011 | MAR | Shivneri (Providing rough S.S.flooring) | 0.55 | 0 | 0.55 | Work In Progress | |
| 2010-2011 | MAR | Shivneri (Improvement of Drainage) | 0.48 | 0 | 0.48 | Work In Progress | |
| 2010-2011 | MAR | Shivneri (Repairs to internal structural repairs) | 4.05 | 0 | 4.05 | Work In Progress | |
| 2010-2011 | MAR | Shivdarshan (Repairs to plaster & painting work) | 8.45 | 0 | 8.45 | Work In Progress | |
| 2010-2011 | MAR | C.R. Work of replacement of damaged in R/c bldg 'Gurusadan' in 'E-2' Ward | 0.50 | 0 | 0.5 | Work In Progress | |
| 2010-2011 | MAR | Om-Niwas, Kamathipura 8th lane (Repair to terrace, water proofing, O.H & U.G tank) | 4.88 | 0 | 4.88 | Work In Progress | |
| 2010-2011 | MAR | Mombattiwala (Repairs to terrace & water proofing & O.H & U.G tank) | 3.97 | 0 | 3.97 | Work In Progress | |
| 2010-2011 | MAR | C.R. Work to providing antitermite tratment to R/c bldg 'Punarjeevan' in 'E-2' Ward | 0.58 | 0 | 0.58 | Work In Progress | |
| 2010-2011 | MAR | Repairs to UG Tank to R/c bldg 'Kranti Sadan', 'Gurukripa' in E-2' Ward | 0.54 | 0 | 0.54 | Work In Progress | |
| 2010-2011 | MAR | Repairs to O.H. & U.G.Tank to R/c bldg 'Navbahar', 'Mombattiwala', 'Aqsa Manzil' in 'E-2' Ward. | 0.55 | 0 | 0.55 | Work In Progress | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|------------------------|-------|--|-----------------------------------|------------------------------------|----------------------|--------------------------------------|---------|
| | | C.R. Work to R/c bldg 'Sai Darshan', 'Shivdarshan' in 'E- | | | | | |
| 2010-2011 | MAR | 2' Ward | 0.55 | 0 | 0.55 | Work In Progress | |
| 2010 2011 | | C.R. Work to R/c bldg 'Jagatsmruti', 'Gharkul', 'Gurusadan' in 'E-2' Ward | 0.50 | | 0.50 | Mark In Deserves | |
| 2010-2011 | | Wrks ext plaster & painting Vignahar | 0.56 | 0 | 0.56 | Work In Progress | |
| 2010-2011 2010-2011 | | Water proofing to Terrace Shradhanand | 9.45 0.85 | 0 | 9.45 0.85 | Work in progress Work in progress | |
| 2010-2011 | | Water proofing to Terrace Sai Siddhi | 0.83 | 0 | 0.83 | Work in progress | |
| 2010-2011 | | Wrks ext plaster & painting Torana | 0.7 | 0 | 0.7 | Work in progress | |
| 2010-2011 | | Repairs 17 kesoji naik to external plaster & painting | 3.41 | 5.1 | 8.51 | Work completed | |
| 2010-2011 | | Wrks ext plaster & painting Vignahar (revised) | 11.25 | 0 | 11.25 | Work in progress | |
| 2010-2011 | | Sweeping cleaning to enements & shops for 13 R.C.Buildings | 0.21 | 0 | 0.21 | WorkCompleted | |
| 2010-2011 | MAR | Repairs to passage Ceiling at Sahyadri Niwas | 0.56 | 0 | 0.56 | WorkCompleted | |
| 2010-2011 | MAR | Repairs to staircase at Sahyadri Niwas | 0.6 | 0 | 0.6 | WorkCompleted | |
| 2010-2011 | MAR | Repairs to G.S.W.Lines & Chambers at Sahyadri Niwas | 0.65 | 0 | 0.65 | WorkCompleted | |
| 2010-2011 | MAR | Repairs to G.S.W.Lines & Inspecton Chambers at Samrat Sadan | 0.62 | 0 | 0.62 | WorkCompleted | |
| 2010-2011 | MAR | Repairs to internal Room Ceiling at Shraddhanand | 0.62 | 0 | 0.62 | WorkCompleted | |
| 2010-2011 | MAR | Repairs to internal Room Ceiling & WC Bath at Sai Siddhi | 0.63 | 0 | 0.63 | WorkCompleted | |
| 2010-2011 | MAR | Repairs to Pump room at Virani house | 0.63 | 0 | 0.63 | WorkCompleted | |
| 2010-2011 | MAR | Repairs to Drainage & Removing debries at Virani house | 0.63 | 0 | 0.63 | WorkCompleted | |
| 2010-2011 | MAR | Repairs to Compound wall & plinth protection at Sai Siddhi | 0.56 | 0 | 0.56 | WorkCompleted | |
| 2010-2011 | MAR | Repairs to G I Pipes & attending leakages at Torana | 0.57 | 0 | 0.57 | WorkCompleted | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|--|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| 2010-2011 | MAR | Repairs to damaged G I Pipes at 17 Kesoji Naik | 0.24 | 0 | 0.24 | WorkCompleted | |
| 2010-2011 | MAR | Attening Complain of Shrt water Supply for tenementsat bajarang Kripa | 0.6 | 0 | 0.6 | WorkCompleted | |
| 2010-2011 | MAR | Attening Complain of Shrt water Supply for tenementsat Sanyadri Niwas | 0.61 | 0 | 0.61 | WorkCompleted | |
| 2010-2011 | | Repairs to G I Pipes & replacement of Broken PVC pipes at Samrat Sadan | 0.44 | 0 | 0.44 | WorkCompleted | |
| 2010-2011 | MAR | Sweeping cleaning to enements & shops for 13 R.C.Buildings | 0.52 | 0 | 0.52 | WorkCompleted | |
| 2010-2011 | MAR | Repairs to internal Room Ceiling at Smarat Sadan | 0.58 | 0 | 0.58 | WorkCompleted | |
| 2010-2011 | MAR | Repairs to internal Room Ceiling at Sanhyadri | 0.62 | 0 | 0.62 | WorkCompleted | |
| 2010-2011 | MAR | Repairs to internal Room Ceiling at Suryodaya | 0.64 | 0 | 0.64 | WorkCompleted | |
| 2010-2011 | . MAR | To cleaning & washing U.G.Tank & O.H.tank for 13 Rc.Buildings | 0.21 | 0 | 0.21 | WorkCompleted | |
| 2010-2011 | MAR | Improvement Of Drainage Line to RC Building Shradhanand | 0.3 | 0 | 0.3 | WorkCompleted | |
| 2010-2011 | MAR | Attending leakage of G I pipes to RC Building Sai Siddhi | 0.29 | 0 | 0.29 | WorkCompleted | |
| 2010-2011 | MAR | CR to RC Building Samrat Sadan & Shyadri Niwas removing Choke Up & tree Cutting | 0.23 | 0 | 0.23 | WorkCompleted | |
| 2010-2011 | MAR | CR to RC Building Shradhanad & Suryodaya removing Chokeup & tree cutting | 0.25 | 0 | 0.25 | WorkCompleted | |
| 2010-2011 | MAR | CR to RC Building Virani House & vifnahar Sadan removing Choke Up & tree Cutting | 0.24 | 0 | 0.24 | WorkCompleted | |
| 2010-2011 | | CR to RC Building Torana Sai Siddhi & Gajanan Krupa removing Choke Up & tree Cutting | 0.22 | 0 | 0.22 | WorkCompleted | |
| 2010-2011 | | Sweeping cleaning to tenements & shops for 13 R.C.Buildings | 0.52 | 0 | 0.52 | WorkCompleted | |



| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|------------------|---------|
| | | SR to RC Building Bajarang Kriparpairs to waterproofing | | | | | |
| 2010-2011 | MAR | to terrace | 5.05 | 0 | 5.05 | WorkCompleted | |
| 2010-2011 | MAR | SR to RC Building 17 -18-21 Kolsa Street Internal & External Repairs | 10.57 | 0 | 10.57 | Work in progress | |
| | | SR to RC Building 17 -18-21 Kolsa StreetWaterproofing to | | | | | |
| 2010-2011 | MAR | terrace | 4.46 | 0 | 4.46 | WorkCompleted | |
| 2010-2011 | MAR | SR to RC Building Moghal | 8.01 | 0 | 8.01 | Work in progress | |
| 2010-2011 | MAR | SR to RC Building Saiphi Manzil | 9.83 | 0 | 9.83 | WorkCompleted | |
| 2010-2011 | MAR | Internal Strctural Repairs to Mahavir Niwas | 10.35 | 0 | 10.35 | Work in progress | |
| 2010-2011 | MAR | Improvement Of Drainage Line to RC Building Suryodaya | 0.59 | 0 | 0.59 | WorkCompleted | |
| 2010-2011 | MAR | C R works to saifee manzil providing chaina Mosaic to terrace | 0.61 | 0 | 0.61 | WorkCompleted | |
| 2010-2011 | MAR | C R works to saifee manzil repairs to daamage & Decayed Doors toilet | 0.54 | 0 | 0.54 | WorkCompleted | |
| 2010-2011 | MAR | C R works toTawakkal repairs to damaged & Decayed Doors toilet | 0.54 | 0 | 0.54 | WorkCompleted | |
| 2010-2011 | MAR | Repairs to Passage& Room Ceiling at Smarat Sadan | 0.43 | 0 | 0.43 | WorkCompleted | |
| 2010-2011 | MAR | Improvement to drainage system to R/C bldg Kalptaru | 0 | 1.93 | 1.93 | Ρ | |
| 2010-2011 | MAR | Improvement to drainage system to R/C bldg Triveni Sadan No.1 | 0 | 6.70 | 6.7 | Ρ | |
| 2010-2011 | MAR | Internal Structural Repairs to R/C bldg Triveni Sadan No.1 | 0 | 10.04 | 10.04 | Ρ | |
| 2010-2011 | . MAR | Repairs to Ceiling Slab Beam, Column T/S room & common passage to R/C bldg Mauli | 3.89 | 2.1 | 5.99 | 2nd R.A. | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| | | Repairs to Staircase Drainage arrangement RCC flooring | _ | | | | |
| 2010-2011 | . MAR | & PVC pipe to R/C bldg Gulzar Mansion | 0 | 8.2 | 8.2 | 1st R.A. | |
| 2010-2011 | MAR | Structural Repairs Plaster & Painting to R/C bldg Shivsahyadri | 0 | 10.9 | 10.9 | Р | |
| | | Structural Repairs Plaster & painting to R/C Bldg | | | | | |
| 2010-2011 | MAR | Sonawala | 0 | 17.61 | 17.61 | Р | |
| 2010-2011 | MAR | External Plaster & Painting to R/C Bldg Sindhudurga | 0 | 9.07 | 9.07 | Р | |
| 2010-2011 | MAR | Improvement Drainage System to R/C Bldg Suryadarshan | 0 | 4.3 | 4.3 | Р | |
| 2010-2011 | MAR | Plaster & Painting to R/C bldg Swapnpurti | 0 | 6.27 | 6.27 | Р | |
| 2010-2011 | MAR | Plaster & Painting to R/C bldg Pittalwala | 0 | 6.3 | 6.3 | Р | |
| 2010-2011 | MAR | External Plaster & painting to R/C Bldg Noorani Manzil | 0 | 4.83 | 4.83 | Р | |
| 2010-2011 | MAR | External Plaster & painting to R/C Bldg Bhuvneshwar | 0 | 14.71 | 14.71 | Р | |
| 2010-2011 | MAR | Replacement damadge decyed windows to R/C bldg Madhav Bhuvan C wing | 0 | 0.58 | 0.58 | С | |
| 2010-2011 | MAR | Repairs to c/p & common Balcony to R/C bldg Manas A-B | 0 | 0.65 | 0.65 | С | |
| 2010-2011 | MAR | Attending Leakages to room nahani & W.C. to R/C bldg Saikrupa A&B wing | 0 | 0.61 | 0.61 | С | |
| 2010-2011 | MAR | repairs to room ceiling plaster to R/C bldg Suryadarshan D- Wing | 0 | 0.62 | 0.62 | С | |
| 2010-2011 | MAR | Sweeping & Cleaning to R/C bldg Sonawala, Shrihari, Shivneri New rajaram Niwas | 0 | 0.59 | 0.59 | С | |
| 2010-2011 | MAR | Sweeping & Cleaning to R/C bldg Triveni Sadan No. 1 & 2 | 0 | 0.29 | 0.29 | С | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| 2010-2011 | MAR | Repairs to Chember of gully trap to R/C bldg Sita Sadan | 0 | 0.59 | 0.59 | С | |
| 2010-2011 | MAR | Sweeping & Cleaning to R/C Bldg Sahakar Bhavan Madhav Bhavan, Laxmi Cottege A&B | 0 | 0.62 | 0.62 | | |
| | | Sweeping & Cleaning to R/C Bldg Chandrodaya, Swapnpurti, Shraddha, Saikrupa | | | | | |
| 2010-2011 | | Sweeping & Cleaning to R/C Bldg Mangalmurti, | 0 | 0.48 | 0.48 | | |
| 2010-2011 | | Mayuresh, Manas, Raigad A-B Sweeping & Cleaning to R/C Bldg Ramdoot 1 to 4 & | 0 | 0.61 | 0.61 | C | |
| 2010-2011 | MAR | Bhuvneshwar Repairs to Damaged S.W.Line Chamber Rough | 0 | 0.62 | 0.62 | С | |
| 2010-2011 | MAR | Shahabad Flooring to R/C bldg Shrikrishan | 0 | 0.59 | 0.59 | С | |
| 2010-2011 | MAR | Sweeping & Cleaning to R/C Bldg Prabhnjan, Mauli, Shrisiddhi, Anant Niwas | 0 | 0.25 | 0.25 | С | |
| 2010-2011 | MAR | Sweeping & Cleaning to R/C Bldg Vighnharta, Morya, AdharAB, Ranveer Sadan, Sankalp | 0 | 0.47 | 0.47 | С | |
| 2010-2011 | MAR | Sweeping & Cleaning to R/C Bldg Kuka Sadan, Kalptaru, Siddhivinayak | 0 | 0.57 | 0.57 | C | |
| 2010-2011 | | Sweeping & Cleaning to R/C Bldg Sindhudurg, Vitthal Sadan, Sadguru Sadan, Shramik | 0 | 0.52 | 0.52 | С | |
| 2010-2011 | | Damaged S.W.line chamber@rough shabad flooring to R/C bldg Ranveer Sadan | 0 | 0.55 | 0.55 | С | |
| 2010-2011 | | Repairs to G.I.Pipe & Gate Valve to R/C bldg Shivneri, ABC | 0 | 1.14 | 1.14 | | |
| 2010-2011 | | Replacement damaged rusted G.S.pipe & Gate valve to R/C bldg Shivneri ABC | 0 | 0.57 | 0.57 | C C | |
| 2010-2011 | | Repairs to U.G.Tank to R/C bldg Gulistan | 0 | 0.35 | 0.35 | C | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|--|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| | | Replacement Damaged decyed W.C. door to R/C bldg | _ | | | | |
| 2010-2011 | MAR | Ranveer Sadan A wing | 0 | 0.61 | 0.61 | C | |
| 2010-2011 | MAR | Removing Leakages from Common W.C. & Bathroom to R/C Bldg Ramdoot No.1 | 0 | 0.62 | 0.62 | С | |
| | | Internal Ceiling Plaster 1st flr,4th & 5th flr to R/C bldg | | | | | |
| 2010-2011 | MAR | Mangalmurti | 0 | 0.61 | 0.61 | С | |
| 2010-2011 | MAR | Internal Ceiling Plaster to R/C bldg Siddhant | 0 | 0.61 | 0.61 | С | |
| 2010-2011 | MAR | Repairs to Siproex Slab Ceiling to R/C bldg Ramdoot No.4 | 0 | 0.59 | 0.59 | С | |
| 2010-2011 | MAR | Replacement of damaged decyed window shutter frame to R/C bldg Ranveer Sadan | 0 | 0.62 | 0.62 | С | |
| 2010-2011 | MAR | Ceiling Plaster & Painting to R/C bldg Shrikrishna Bhavan | 0 | 0.44 | 0.44 | С | |
| 2010-2011 | MAR | Removing Leakages from Common W.C. & Bathroom to R/C Bldg Ramdoot No.2 | 0 | 0.57 | 0.57 | С | |
| 2010-2011 | MAR | Repairs to External Parapet Wall & room ceiling plaster to R/C bldg Prabhnjan | 0 | 0.66 | 0.66 | С | |
| 2010-2011 | MAR | Attending Leakages to roo Nahani to R/C bldg Raigad Niwas No.1 | 0 | 0.6 | 0.6 | С | |
| 2010-2011 | MAR | P/F Collapsible still gate to R/C bldg Suryadarshan A-B Wing | 0 | 0.18 | 0.18 | С | |
| 2010-2011 | | Repairs to RCC pardi & c/p ceiling at 1st 2nd & 3rd flr to R/C bldg Prabhanjan | 0 | 0.65 | 0.65 | С | |
| 2010-2011 | | Attending Leakages to room Nahani & W.C. to R/C bldg Manas | 0 | 0.57 | 0.57 | | |
| 2010-2011 | | P/F collapsible steel gate to R/C bldg Suryadarshan C&D Wing | 0 | 0.18 | 0.18 | C | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|--|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| | | Repairs to Siproex Slab Ceiling to R/C bldg Ramdoot No.1 | | | | | |
| 2010-2011 | MAR | & 2 | 0 | 0.61 | 0.61 | C | |
| 2010-2011 | MAR | Attending Leakages to W.C. & Bath to R/C bldg Shrihari | 0 | 0.51 | 0.51 | С | |
| | | Repairs to G.I.pipe in MCGM line shahabad flooring & | | | | | |
| 2010-2011 | MAR | Meter Chamber to R/C bldg Amardeep | 0 | 0.61 | 0.61 | С | |
| | | Replacement of Damaged S.W.line rough shahabad | | | | | |
| 2010-2011 | MAR | flrring to R/C bldg Mayuresh | 0 | 0.56 | 0.56 | С | |
| 2010-2011 | MAR | Repairs to Ceiling Plaster to R/C bldg Shraddha | 0 | 0.43 | 0.43 | С | |
| 2010-2011 | MAR | Replacing S.W. line to R/C bldg New Rajarm Niwas | 0 | 1.11 | 1.11 | С | |
| 2010-2011 | MAR | RCC menber in the building to R/C bldg Siddhivinayak | 0 | 0.56 | 0.56 | С | |
| 2010-2011 | MAR | Shop Ceiling Plaster to R/C bldg Raigad Niwas No.1 | 0 | 0.61 | 0.61 | С | |
| 2010-2011 | MAR | Sewarage Plinth protection Compound Wall to R/C bldg Noorani Manzil | 0 | 0.26 | 0.26 | С | |
| 2010-2011 | MAR | Siporex Ciling Slab to R/Cbldg Sita Sadan | 0 | 0.59 | 0.59 | С | |
| 2010-2011 | MAR | Replacement of Damaged Decyed window & W.C. Doors to R/C bldg Madhav Bhuvan, Saikrupa | 0 | 0.58 | 0.58 | С | |
| | | Replacement of Damaged S.W.line & Chambers P/L rough shahabad flrring to R/C bldg Ranveer Sadan 'B- | | | | | |
| 2010-2011 | MAR | Wing' | 0 | 0.50 | 0.5 | C | |
| | | Repairs to Chamber Gully Trap, Rough Shahabad Flooring & Prov. Out Side Plaster to Pumproom to R/C | | | | | |
| 2010-2011 | MAR | bldg Bhakti, Trimurti | 0 | 0.60 | 0.6 | С | |
| 2010-2011 | MAR | Providing anti termite treatment at r.c.bldg.Chintamani at Dadar() | 0.75 | 0 | 0.75 | completed | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|--|-----------------------------------|------------------------------------|----------------------|------------------|---------|
| | | Sweeping & cleaning at r.c.building at | | | | | |
| 2010-2011 | MAR | r.c.bldg.Rajhans,Dadar(E) | 0.24 | 0 | 0.24 | completed | |
| 2010-2011 | MAR | Sweeping & cleaning at r.c.building at r.c.bldg.Chintamani,Dadar(E) | 0.17 | 0 | 0.17 | completed | |
| | | Providing anti termite treatment at r.c.bldg.Rajhans at | | | | | |
| 2010-2011 | MAR | Dadar() | 0.44 | 0 | 0.44 | completed | |
| | | S.R. works to reconstructed Bldg. Chintamani at Dadar | | | | | |
| 2010-2011 | MAR | (E) | 0 | 0 | 0 | Work in progress | |
| | | Repair to loose / damaged ceiling of reconstructed bldg. | | | | | |
| 2010-2011 | MAR | Hirkani at B.S. Road, Dadar | 3.9 | | 3.9 | completed | |
| 2010-2011 | MAR | Repair to ceiling and wall plaster in patch to reconstructed bldg. known as Kalika Darshan, Dadar Repair to loose / damaged ceiling of reconstructed bldg. | 1.61 | | 1.61 | completed | |
| 2010-2011 | MAR | Gulmohar, K.V.Chitale Path, Dadar | 0.57 | | 0.57 | completed | |
| 2010-2011 | | Repair to loose /damaged ceiling of reconstructed bldg. Gulmohar in G/N ward. | 0.65 | | 0.65 | completed | |
| 2010-2011 | MAR | Attending of leakages of w.c. / bath of T,S, no. 16,17,24,25,31,32,76,78 common washing place attending leakage of G.I. pipt of r/c bldg. Gulmohar. | 0.6 | | 0.6 | completed | |
| 2010-2011 | MAR | Repair to PVC drainage pipes, attending complaint of leakages in shop no. 6 &7, Room no. 318, etc of R/c bldg. Sai Ganesh Sadan, Dadar(W.) | 0.5 | | 0.5 | completed | |
| 2010-2011 | MAR | Attending leakages through Nahani, w.c. / bath in R/c bldg. known as Kalika Darshan, Dadar(W.) | 0.43 | | 0.43 | completed | |
| 2010-2011 | MAR | S.R. to reconstructed bldg. Gulmohar in G/N Div Providing water proofing to terrace. | 2.79 | | 2.79 | completed | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|--|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| 2010 2011 | | S.R. to R/c bldg. known as Kalika Darshan in G/N ward, | 11.2 | | 11.2 | | |
| 2010-2011 | MAR | Plastering and Painting. | 11.2 | | 11.2 | completed | - |
| 2010-2011 | MAR | Cleaning of U.G.T. and overhead tank of Sudarshan bldg.at Dadar. | 0.08 | | 0.08 | completed | |
| | | Cleaning of U.G.T. and overhead tank of Hirkani bldg.at | | | | | |
| 2010-2011 | MAR | Dadar. | 0.19 | | 0.19 | completed | |
| 2010 2011 | | Cleaning of U.G.T. and overhead tank of Sai Ganesh | 0.40 | | 0.40 | | |
| 2010-2011 | MAR | Sadan bldg.at Dadar. | 0.18 | | 0.18 | completed | |
| 2010-2011 | MAR | Cleaning of U.G.T. and overhead tank of Ratnabhoomi bldg.at Dadar. | 0.07 | | 0.07 | completed | |
| | | Cleaning of U.G.T. and overhead tank of Mayuri bldg.at | | | | | |
| 2010-2011 | MAR | Dadar. | 0.1 | | 0.1 | completed | |
| 2010-2011 | MAR | Cleaning of U.G.T. and overhead tank of Gulmohar bldg.at Dadar. | 0.11 | | 0.11 | completed | |
| | | Cleaning of U.G.T. and overhead tank of Nandanvan | | | | · | |
| 2010-2011 | MAR | bldg.at Dadar. | 0.11 | | 0.11 | completed | |
| | | Cleaning of U.G.T. and overhead tank of Tapsya bldg.at | | | | | |
| 2010-2011 | MAR | Dadar. | 0.06 | | 0.06 | completed | |
| | | Cleaning of U.G.T. and overhead tank of Kalika Darshan | | | | | |
| 2010-2011 | MAR | in G/N ward | 0.3 | | 0.3 | completed | |
| | | Providing water proofing to over head tank to R/c bldg. of | | | | | |
| 2010-2011 | MAR | C-wing known as Hirkani in G/N ward | 0.62 | | 0.62 | completed | |
| | | Repair to common w.c. at ground floor , repair to gate | | | | | |
| 2010-2011 | MAR | volve, G.I. pipe at R/c bldg. Nandanvan,Dadar. | 0.55 | | 0.55 | completed | |
| | | Repair to loose damaged ceiling of R/c bldg. Sai Ganesh | | | | | |
| 2010-2011 | MAR | Sadan in G/N ward | 0 | | 0 | completed | |
| | | complaint of leakages of overhead tank of R/c bldg. | | | | | |
| 2010-2011 | MAR | Sudarshan, Gokhale Road, Dadar. | 0.63 | | 0.63 | completed | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| | | C.R. work to reconstructed bldg. Shivshai Sadan, Repair | | | | | |
| 2010-2011 | MAR | to G.I. pipe | 0.22 | | 0.22 | completed | |
| 2010-2011 | MAR | C.R. to reconstructed bldg. Shreyas bldg. to pipe line and its fitting | 0.25 | | 0.25 | completed | |
| 2010-2011 | MAR | C.R. work to reconstructed bldg. Shivshai Sadan, reparis to loose pealed internal plaster | 0.13 | | 0.13 | completed | |
| 2010-2011 | MAR | C.R. work to reconstructed bldg. Shreyas repair to flooring of G.F. Passage | 0.42 | | 0.42 | completed | |
| 2010-2011 | MAR | S.R. work to reconstructed bldg. Shivshahi Sadan,- Plastering and Painting | 4.62 | | 4.62 | completed | |
| 2010-2011 | MAR | cleaning of UGT of OHT of reconstructed bldg. Gajanan Krupa, Shivshahi, Kulshree, Ram niwas, shreyas, Akansha | 0 | 0.11 | 0.11 | completed | |
| 2010-2011 | MAR | C.R. work in respect of removing trees, removing chockages, repairs to PVC pipe to reconstructed bldg. GajananKrupa, Shreyas, Kulshree | 0 | 0.35 | 0.35 | completed | |
| 2010-2011 | MAR | C.R. work in respect of repairs to G.I.pipe at terrace level and down take for the reconstructed bldg. known as Akansha. | 0 | 0.25 | 0.25 | completed | |
| 2010-2011 | MAR | C.R. work to R/c bldg. known as Shivshahi Sadan at R.K. Vaidya Road, Dadar | 0.58 | 0 | 0.58 | completed | |
| 2010-2011 | MAR | C.R. work in repairs of ceiling and beam (Collapsed ceiling) at room no. 26 and danger portion of ceiling in common passage and toilet block of r/c bldg. known as Shreyas bldg. N.C. Kelkar Road, Dadar/ | 0 | 0.48 | 0.48 | completed | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS | REMARKS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|----------------|---------|
| | | C.R. work in respect of removing danger portion at ceiling | | | | | |
| | | and repairs to ceiling and repairs to ceiling and flooring at | | | | | |
| | | room no. 10 at r/c bldg. known as Akansha at N.C.Kelkar | | | | | |
| 2010-2011 | MAR | Marg, Dadar. | 0 | 0.58 | 0.58 | completed | |
| | | C.R. to R/c bldg. Ram Bhavan G/N ward - Providing | | | | | |
| 2010-2011 | MAR | 25mm dias G.I.P. | 0.24 | 0 | 0.24 | completed | |
| 2010 2011 | | S.R. work to R/c bldg. Ram Bhavan - Plastering & | | 2.47 | | | |
| 2010-2011 | MAR | Painting. C.R. work to providing Antiternite treatment to R/c bldg. | 0 | 3.47 | 3.47 | completed | |
| 2010-2011 | | known as 'Aakansha' in G/N ward. | 0 | 0.24 | 0.24 | completed | |
| 2010-2011 | IVIAR | C.R. work to providing antiternite treatment to R/c bldg. | 0 | 0.24 | 0.24 | completed | |
| 2010-2011 | MAR | known as 'Shreyas' in G/N ward. | 0 | 0.26 | 0.26 | completed | |
| 2010-2011 | | C.R. work to providing antiternite treatment to R/c bldg. | 0 | 0.20 | 0.20 | completed | |
| 2010-2011 | MAR | known as 'Kulshree' in G/N ward. | 0 | 0.17 | 0.17 | completed | |
| | | C.R. work to providing antiternite treatment to R/c bldg. | | | | | |
| 2010-2011 | MAR | known as 'Shivshahi Sadan' in G/N ward. | 0 | 0.18 | 0.18 | completed | |
| 2010-2011 | | Sweeping & Cleaning of r/c bldg. Mayuri, Kalikadarshn, Gulmohar, Shri.sai ganesh sadan, Ratnabhoomi, Tapasya, Hirkani, Nandanvan in G/N ward. | 0.5 | 0 | 0.5 | completed | |
| 2010-2011 | MAR | Sweeping & Cleaning of r/c bldg. Mayuri, Kalikadarshn, Gulmohar, Shri.sai ganesh sadan, Ratnabhoomi, Tapasya, Hirkani, Nandanvan in G/N ward. | 0.25 | 0 | 0.25 | completed | |
| 2010-2011 | MAR | S.R. of rep. to windows w.c. door for t/s no. 102,104, 112, 301, 402, 412, 506, 001, 002, 003, 202, 203,209, 306, 313, 406, 413, 302, 211, 509 no. at Sudarshan bldg. Gokhale Rd. Dadar(w.) | 0.49 | 0 | 0.49 | completed | |





| YEAR | MONTH | WORK NAME | EXPENDITURE UPTO LAST MONTH | EXPENDITURE IN CURRENT MONTH | TOTAL EXPENDITURE | CURRENT STATUS |
|-----------|-------|---|-----------------------------------|------------------------------------|----------------------|----------------|
| | | S.R. work in respect of attending the compliant of | | | | |
| | | damaged w.c. door of room no. 101, 201, 105, 202, 301, 304, 307, 402, 404, 412, 503 & 509 at R/c bldg. | | | | |
| 2010-2011 | MAR | 'Sudarshan' Gokhale Road, Dadar. | 0.63 | 0 | 0.63 | completed |
| | | S.R. work to R/c bldg. Mayuri in G/N ward Providing water | | | | |
| 2010-2011 | MAR | proofing to terrace & overhead tank. | 1.2 | 0 | 1.2 | completed |
| 2010-2011 | MAR | S.R. work in respect of attending the compliant of damaged door of common w.c. bath at reconstructed bldg. Sai Ganesh Sadan, S.B. Marg, Dadar | 0.18 | 0 | 0.18 | completed |
| 2010-2011 | MAR | S.R. work to r/c bldg. Shalimar at Kapad Bazar, in G/N ward Plastering & Painting. | 0 | 5.76 | 5.76 | completed |
| 2010-2011 | MAR | S.R. work to r/c bldg. Nellai Mahal in G/N ward Plastering & Painting. | 0 | 6.13 | 6.13 | completed |
| 2010-2011 | MAR | S.R. work to r/c bldg. Tapasya at Bhavani Shankar Road, in G/N ward Plastering & Painting. | 0 | 7.72 | 7.72 | completed |



| S | REMARKS |
|---|---------|
| | |
| | |
| | |
| | |
| | |
| | |